

SHIP8, INC.

ATTN: ACCOUNTS PAYABLE
45875 NORTHPORT LOOP EAST
FREMONT, CA 94538
US
AP.SHIP8@SHIP8.COM

PO No.

24030240

PO Date

03/06/2024

Page

1 OF 1

ORDER FROM

1069

LIFT POWER INC.

JACKSONVILLE, FL 32254

SHIP TO

SD2(2000),
SHIP8, INC.
ATTN: CHRISTINE JENKINS
550 NORTHPORT PARKWAY
PORT WENTWORTH, GA 31407
US

Buyer

Purchasing Dept

Terms

Net 30 Days

FOB

FOB Origin

Ship Via

Best possible

| Line No. | Vendor Item No. | Vendor Item Description | Qty Ordered | UOM | Unit Price | Extended Price |
|----------|-----------------|-------------------------|-------------|------|------------|----------------|
| 1 | 060000-051 | PIN ROLL <i>3-6 2m</i> | 1.00 | Each | 0.45 | |
| 2 | EQU021 | LABOR <i>3-6 2m</i> | 1.00 | Each | 66.15 | |

Total Extended Price =

LIFTPOWER

Industrial Trucks • Materials Handling Equipment

801 Suemac Place

Jacksonville, FL 32254

(904) 783-0250 | Fax (904) 781-1451

Order # 340094917

Reference # 934005138

Open Date 2/28/2024

Terms - Net 30

Writer: JONATHAN GA

Road Service Order

Salesman: House CSSR

CALL

TO: 7253
SHIP8 INC
45875 NORTHPORT LOOP EAST
Fremont, CA 94538
510-490-9788

SHIP

TO: 7256
SHIP8 INC
SD2
550 NORTHPORT PKWY
Savannah, GA 31407
510-490-9788

| Job # | Ship Via | FOB | Make | Model | Serial # | Unit # | Meter |
|-------|----------|-----|-------|-----------|----------|--------|-------|
| | | | CROWN | SP3520-30 | 1A364712 | OP31 | 4183 |

Note to replace broken roll pin on RH side.

Contact:
jv.maint@ship8.com

WORK PERFORMED: From PM follow up. Found broken roll pin RHF load wheel. One side was broken off, other side chipped off. Took punch to flat end, attempted to tap out, no movement, took torch to axle to heat, attempted knocking out again. Able to remove roll pin, axle is OK. Installed new roll pin. Test drive, check axle. Lift returned to service.
Jonathan Gambrall (2024-02-28)

| Part # | Whse | Description | Bin | Qty | BO | Shipped | Each | Extended |
|-----------|-------|-------------|------|-----|----|---------|------|----------|
| 50000-051 | V3139 | PIN ROLL | 15B2 | 1 | 0 | 1 | 0.45 | 0.45 |
| | | | | | | | | 66.15 |

Need to place a service call?

Please visit our website www.liftpower.com, click on service request, fill out the form and click submit. The next available service technician will be dispatched to you.

Receivables sent to collections will be subject to additional costs associated with collection of a debt over and above the original debt amount.

| | |
|-----------|---------|
| Sub Total | \$66.60 |
| Tax | \$0.03 |
| Total | \$66.63 |



Search in mail



- Compose
- Inbox
- Starred
- Snoozed
- Sent
- Drafts
- More

Labels

PO Request for Lift Power - SD2 - Quote # 340094917 Inbox x

329



James Burford

Christine, Please create a PO for the attached. James Burford Regional Facilities Director 311 International Trade Pkwy Port



Christine Jenkins

PO 24030240 attached Christine Jenkins Purchasing Coordinator 550 Northpon Parkway Port Wentworth, GA 31407 O:912



James Burford

to me, SAV.maint.management

This PO is completed



SHIP8 INC.

James Burford
Regional Facilities Director
311 International Trade Pkwy
Port Wentworth, GA 31407

C:912.507.7881

Order received, thank you.

Received, thank you.

Thank you.

Reply

Reply all

Forward



Industrial Trucks • Materials Handling Equipment

801 Suemac Place
Jacksonville, FL 32254
(904) 783-0250 | Fax (904) 781-1451

Inv # 340094917
Reference # 934005138
Inv Date 3/6/2024
Terms - Net 30
Writer: JONATHAN GA

Road Service Invoice

Salesman: House CSSR

CALL TO: 7253
SHIP8 INC
45875 NORTHPORT LOOP EAST
Fremont, CA 94538
510-490-9788

SHIP TO: 7256
SHIP8 INC
SD2
550 NORTHPORT PKWY
Savannah, GA 31407
510-490-9788

| PO # | Ship Via | FOB | Make | Model | Serial # | Unit # | Meter |
|---------|----------|-----|-------|-----------|----------|--------|-------|
| 1030240 | | | CROWN | SP3520-30 | 1A364712 | OP31 | 4183 |

Quote to replace broken roll pin on RH side.

Contact:
jv.maint@ship8.com

WORK PERFORMED: From PM follow up. Found broken roll pin RHF load wheel. One side was broken off, other side chipped off. Took punch to flat end, attempted to tap out, no movement, took torch to axle to heat, attempted knocking out again. Able to remove roll pin, axle is OK. Installed new roll pin. Test drive, check axle. Lift returned to service.
Jonathan Gambrell (2024-02-28)

| Part # | Whse | Description | Bin | Qty | BO | Shipped | Each | Extended |
|-----------|-------|-------------|------|-----|----|---------|------|----------|
| 50000-051 | V3139 | PIN ROLL | 15B2 | 1 | 0 | 1 | 0.45 | 0.45 |
| labor | | | | | | | | 66.15 |

Need to place a service call?
Please visit our website www.liftpower.com, click on service request, fill out the form and click submit. The next available service technician will be dispatched to you.

voices sent to collections will be subject to additional costs associated with collection of a debt over and above the original debt amount.

| | |
|-----------|---------|
| Sub Total | \$66.60 |
| Tax | \$0.03 |
| Total | \$66.63 |