

SHIP8, INC.

ATTN: ACCOUNTS PAYABLE
 45875 NORTHPORT LOOP EAST
 FREMONT, CA 94538
 US
 AP.SHIP8@SHIP8.COM

PO No.

24030245

PO Date

03/06/2024

Page

1 OF 1

ORDER FROM

1069

LIFT POWER INC.

JACKSONVILLE, FL 32254

SHIP TO

SD2(2000),
 SHIP8, INC.
 ATTN: CHRISTINE JENKINS
 550 NORTHPORT PARKWAY
 PORT WENTWORTH, GA 31407
 US

Buyer

Purchasing Dept

Terms

Net 30 Days

FOB

FOB Origin

Ship Via

Best possible

Line No.	Vendor Item No.	Vendor Item Description	Qty Ordered	UOM	Unit Price	Extended Price
1	060000-051	PIN ROLL <i>3-4</i>	2.00	Each	0.45	
2	363004-001	GREASE JT6 MULTIPURPOSE 14OZ <i>3-4</i>	1.25	Each	11.95	
3	363116-001	BRAKE CLEANER NONFLAMMABLE-CAN <i>3-4</i>	1.00	Each	10.94	
4	EQU021	LABOR <i>3-6</i>	1.00	Each	198.45	

Total/Extended Price =



Industrial Trucks • Materials Handling Equipment

801 Suemac Place
Jacksonville, FL 32254
(904) 783-0250 | Fax (904) 781-1451

Order # 340094967
Reference # 347050255
Open Date 2/29/2024
Terms - Net 30
Writer: JONATHAN GA

Road Service Order

Salesman: House CSSR

CALL TO: 7253
SHIP8 INC
45875 NORTHPORT LOOP EAST
Fremont, CA 94538
510-490-9788

SHIP TO: 7256
SHIP8 INC
SD2
550 NORTHPORT PKWY
Savannah, GA 31407
510-490-9788

Job #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
			CROWN	SP3520-30	1A590071	OP54	2338

Replace RH flatspotted loadwheels. ****CUSTOMER SUPPLIED PARTS**** NTE \$500. Tech PMFU req Jonathan G.

WORK PERFORMED: From PM follow up. RH load wheels had flat spots and pieces missing. Drive tire crumbling. Bad vibration. Took lift to work area. Customer provided parts. Raised up front of lift, and blocked off. set drive to tow. Flipped brake off. Dismounted drive tire, removed tire, slipped new tire underneath, mounted, bolted in, torqued to spec. Removed from tow back into drive, set switch back to drive. Raised lift and removed blocks. Brought jack to H side, blocked off. Knocked out roll pins, knocked out axles. Removed load wheels. Pre-greased new load wheels, shimmed up properly. Ran axles through, stalled new roll pins. Greased up load wheels. Raised up jack. Removed blocks, test drove lift, lift rides much smoother. Returned lift to service.
Jonathan Gambrall (2024-02-29)

Part #	Whse	Description	Bin	Qty	BO	Shipped	Each	Extended
50000-051	V3139	PIN ROLL	15B2	2	0	2	0.45	0.90
53004-001	V3139	GREASE JT6 HIGH TEMP 14OZ	S2	1.25	0	1.25	11.95	14.94
53116-001	V3139	BRAKE CLEANER NONFLAMM...	S3	1	0	1	10.94	10.94
								198.45

Need to place a service call?

Please visit our website www.liftpower.com, click on service request, fill out the form and click submit. The next available service technician will be dispatched to you.

voices sent to collections will be subject to additional costs associated with collection of a debt over and above the original debt amount.

Sub Total	\$225.23
Tax	\$1.87
Total	\$227.10



Search in mail



- 99+
- Compose
- Mail
- Inbox
- Starred
- Snoozed
- Sent
- Drafts
- More

Labels

324

PO Request for Lift Power - SD2 - Quote # 340094967

Inbox x



James Burford

Christine, Please create a PO for the attached. James Burford Regional Facilities Director 311 International Trade Pkwy Port



Christine Jenkins

PO 24030245 attached Christine Jenkins Purchasing Coordinator 550 Northport Parkway Port Wentworth, GA 31407 O:912:



James Burford

to me, SAV.maint.management

PO Completed



SHIP8 INC.

James Burford
Regional Facilities Director
311 International Trade Pkwy
Port Wentworth, GA 31407

C:912.507.7881

- Reply
- Reply all
- Forward

Inv # 340094967
 Reference # 347050255
 Inv Date 3/6/2024
 Terms - Net 30
 Writer: JONATHAN GA

Road Service Invoice

Salesman: House CSSR

BILL TO:
 7253
 SHIP8 INC
 45875 NORTHPORT LOOP EAST
 Fremont, CA 94538
 510-490-9788

SHIP TO:
 7256
 SHIP8 INC
 SD2
 550 NORTHPORT PKWY
 Savannah, GA 31407
 510-490-9788

PO #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
1030245			CROWN	SP3520-30	1A590071	OP54	2338

replace RH flatspotted loadwheels. ****CUSTOMER SUPPLIED PARTS**** NTE \$500. Tech PMFU req Jonathan G.

WORK PERFORMED: From PM follow up. RH load wheels had flat spots and pieces missing. Drive tire crumbling. Bad vibration. Took lift to work area. Customer provided parts. Raised up front of lift, and blocked off, set drive to tow. Flipped brake off. Dismounted drive tire, removed tire, slipped new tire underneath, mounted, bolted in, torqued to spec. Removed from tow back into drive, set switch back to drive. Raised lift and removed blocks. Brought jack to H side, blocked off. Knocked out roll pins, knocked out axles. Removed load wheels. Pre-greased new load wheels, shimmed up properly. Ran axles through, stalled new roll pins. Greased up load wheels. Raised up jack. Removed blocks, test drove lift, lift rides much smoother. Returned lift to service. Jonathan Gambrell (2024-02-29)

Part #	Whse	Description	Bin	Qty	BO	Shipped	Each	Extended
50000-051	V3139	PIN ROLL	15B2	2	0	2	0.45	0.90
53004-001	V3139	GREASE JT6 HIGH TEMP 14OZ	S2	1.25	0	1.25	11.95	14.94
53116-001	V3139	BRAKE CLEANER NONFLAMM...	S3	1	0	1	10.94	10.94
labor								198.45

Need to place a service call?

Please visit our website www.liftpower.com, click on service request, fill out the form and click submit. The next available service technician will be dispatched to you.

voices sent to collections will be subject to additional costs associated with collection of a debt over and above the original debt amount.

Sub Total \$225.23
 Tax \$1.87
 Total \$227.10