

SHIP8, INC.

ATTN: ACCOUNTS PAYABLE
45875 NORTHPORT LOOP EAST
FREMONT, CA 94538
US
AP.SHIP8@SHIP8.COM

PO No.

24030242

PO Date

03/06/2024

Page

1 OF 1

ORDER FROM

1069

LIFT POWER INC.

JACKSONVILLE, FL 32254

SHIP TO

SD2(2000),
SHIP8, INC.
ATTN: CHRISTINE JENKINS
550 NORTHPORT PARKWAY
PORT WENTWORTH, GA 31407
US

Buyer

Purchasing Dept

Terms

Net 30 Days

FOB

FOB Origin

Ship Via

Best possible

Line No.	Vendor Item No.	Vendor Item Description	Qty Ordered	UOM	Unit Price	Extended Price
1	EQU021	LABOR EPJ12 SN: 10173955	1.00	Each	132.30	

3-6 PM U.

Total Extended Price =



Industrial Trucks • Materials Handling Equipment

801 Suemac Place
Jacksonville, FL 32254
(904) 783-0250 | Fax (904) 781-1451

Order # 340094842
Reference # 347050241
Open Date 2/26/2024
Terms - Net 30
Writer: Jonathan G

Road Service Order

Salesman: House CSSR

CALL TO: 7253
SHIP8 INC
45875 NORTHPORT LOOP EAST
Fremont, CA 94538
510-490-9788

SHIP TO: 7256
SHIP8 INC
SD2
550 NORTHPORT PKWY
Savannah, GA 31407
510-490-9788

Q #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
			CROWN	PE4500-60	10173955	EPJ12	1914

Code 336 // Tech req Jonathan G

WORK PERFORMED: Follow up from PM. During travel PE coded out 336. Test drove around section of warehouse, code popped up multiple times on forward. Took PE to work area. Looked up code. Removed panel to handle, found fwd switch was loose, made adjustment and tightened down. Reinstalled panel, took lift for test trip around section of warehouse. Code is no longer coming up after adjustment. Tested fwd/Rev, raise/lower while traveling. PE operates correctly, returning to service.
Jonathan Gambrell (2024-02-26)

Part #	Whse	Description	Bin	Extended
				132.30

Need to place a service call?
Please visit our website www.liftpower.com, click on service request, fill out the form and click submit. The next available service technician will be dispatched to you.

Accounts sent to collections will be subject to additional costs associated with collection of a debt over and above the original debt amount.

Sub Total	\$132.30
Tax	\$0.00
Total	\$132.30



Search in mail



- Compose
- Inbox 324
- Starred
- Snoozed
- Sent
- Drafts 1
- More

Labels

PO Request for Lift Power - SD2 - Quote # 340094842

Inbox x



James Burford

Christine, Please create a PO for the attached, James Burford Regional Facilities Director 311 International Trade Pkwy Port



Christine Jenkins

PO 24030242 attached Christine Jenkins Purchasing Coordinator 550 Northport Parkway Port Wentworth, GA 31407 O.912.



James Burford

to me, SAV.maint.management

PO Completed



SHIP8 INC.

James Burford
Regional Facilities Director
311 International Trade Pkwy
Port Wentworth, GA 31407

C:912.507.7881

- Reply
- Reply all
- Forward



Industrial Trucks • Materials Handling Equipment

801 Suemac Place
Jacksonville, FL 32254
(904) 783-0250 | Fax (904) 781-1451

Inv # 340094842
Reference # 347050241
Inv Date 3/6/2024
Terms - Net 30
Writer: Jonathan G

Road Service Invoice

Salesman: House CSSR

CALL TO: 7253
SHIP8 INC
45875 NORTHPORT LOOP EAST
Fremont, CA 94538
510-490-9788

SHIP TO: 7256
SHIP8 INC
SD2
550 NORTHPORT PKWY
Savannah, GA 31407
510-490-9788

Job #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
1030242			CROWN	PE4500-60	10173955	EPJ12	1914

Code 336 // Tech req Jonathan G

WORK PERFORMED: Follow up from PM. During travel PE coded out 336. Test drove around section of warehouse, code popped up multiple times on forward. Took PE to work area. Looked up code. Removed panel to handle, found fwd switch was loose, made adjustment and tightened down. Reinstalled panel, took lift for test trip around section of warehouse. Code is no longer coming up after adjustment. Tested fwd/Rev, raise/lower while traveling. PE operates correctly, returning to service.
Jonathan Gambrall (2024-02-26)

Part #	Whse	Description	Bin	Extended
				132.30

Need to place a service call?
Please visit our website www.liftpower.com, click on service request, fill out the form and click submit. The next available service technician will be dispatched to you.

Accounts sent to collections will be subject to additional costs associated with collection of a debt over and above the original debt amount.

Sub Total	\$132.30
Tax	\$0.00
Total	\$132.30