

SHIP8, INC.

ATTN: ACCOUNTS PAYABLE
 45875 NORTHPORT LOOP EAST
 FREMONT, CA 94538
 US
 AP.SHIP8@SHIP8.COM

PO No.

24030252

FO Date

03/06/2024

Page

1 OF 1

ORDER FROM

1069

LIFT POWER INC.

JACKSONVILLE, FL 32254

SHIP TO

SD2(2000),
 SHIP8, INC.
 ATTN: CHRISTINE JENKINS
 550 NORTHPORT PARKWAY
 PORT WENTWORTH, GA 31407
 US

Buyer

Purchasing Dept

Terms

Net 30 Days

FOB

FOB Origin

Ship Via

Best possible

Line No.	Vendor Item No.	Vendor Item Description	Qty Ordered	UOM	Unit Price	Extended Price
1	EQU021	LABOR 3-8 Inv.	1.00	Each	417.90	
2	128334-001	Steer Motor Fastener Kit 3-8 Inv.	2.00	Each	92.55	
3	363116-001	BRAKE CLEANER NONFLAMMABLE-CAN 3-8 Inv.	1.00	Each	10.94	
4	MSC023-SHIPPING/FREIGHT	INBOUND FREIGHT QUOTE 3-8 Inv.	1.00	Each	35.00	

Total Extended Price =

LIFTPOWER

Industrial Trucks • Materials Handling Equipment

801 Suemac Place
Jacksonville, FL 32254
(904) 783-0250 | Fax (904) 781-1451

Quote # 934005150
Reference # 347050244
Quote Date 3/4/2024
Terms - Net 30
Writer: *MARCUS B*

Road Service Quote

Salesman:

CALL
FROM: 7253
SHIP8 INC
45875 NORTHPORT LOOP EAST
Fremont, CA 94538
510-490-9788

SHIP
TO: 7256
SHIP8 INC
SD2
550 NORTHPORT PKWY
Savannah, GA 31407
510-490-9788

Q #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
			CROWN	RR5010-35	1A232906	RT14	5700

Note to extract and replace steer hydraulic motor mounting hardware.

This is a recommended repair from a recent PM.

DC:
James Burford
burford@ship8.com

Part #	Whse	Description	Bin	Qty	Each	Extended
28334-001	SAV	STEER MOTOR FASTENER KIT	16B1	2	92.55	185.10
53116-001	SAV	BRAKE CLEANER NONFLAMM...	07A	1	10.94	10.94
Estimated Inbound Freight Labor				1		35.00
						417.90

This Quotation is valid for 30 days.
This Quotation is subject to +/- 10% variation based on cost (Freight is only an estimate).
Any Additional work found will be quoted for customer approval.

Sub Total	\$648.94
Tax	\$16.17
Total	\$665.11



Search in mail



- Compose
- Mail
- Chat
- Meet
- Inbox 319
- Starred
- Snoozed
- Sent
- Drafts 2
- More

Labels

If you did not intend to receive this email, please contact your administrator.



One attachment • Scanned by Gmail



James Burford
to Christine

PO completed 24030252

James Burford
Regional Facilities Director
311 International Trade Pkwy
Port Wentworth, GA 31407

C:912.507.7881

Reply Forward



Christine Jenkins <christine.jenkins@ship8.com>
to James ▾

James

Why do they charge for inbound freight if nothing was shipped?

And I don't see brake cleaner on the invoice, was it not used?



SHIP8 INC.

Christine Jenkins
Purchasing Coordinator
550 Northport Parkway
Port Wentworth, GA 31407

O:912.373.7778 x 3751



James Burford
to me ▾

The Steer motor Fastener Kit might have been shipped. I am not sure on the brake cleaner, might not have billed us for that portion.



SHIP8 INC.

James Burford
Regional Facilities Director
311 International Trade Pkwy
Port Wentworth, GA 31407

C:912.507.7881



Industrial Trucks • Materials Handling Equipment

801 Suemac Place
Jacksonville, FL 32254
(904) 783-0250 | Fax (904) 781-1451

Inv # 340095159

Reference # 934005150

Inv Date 3/7/2024

Terms - Net 30

Writer: *MARCUS B*

Road Service Invoice

Salesman:

CALL

TO: 7253
SHIP8 INC
45875 NORTHPORT LOOP EAST
Fremont, CA 94538
510-490-9788

SHIP

TO: 7256
SHIP8 INC
SD2
550 NORTHPORT PKWY
Savannah, GA 31407
510-490-9788

PO #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
1030252			CROWN	RR5010-35	1A232906	RT14	5700

quote to extract and replace steer hydraulic motor mounting hardware.

this is a recommended repair from a recent PM.

DOC:
James Burford
james.burford@ship8.com

WORK PERFORMED: Travelled to shop. Picked up parts. Returned to site. Located lift, and moved to work area. Uninstalled steer motor. Removed mounting hardware. With difficulty, extracted broken bolt from well in articulation plate. Re-tapped and threaded. Installed new hardware. Reinstalled steer motor. Tested and returned to service
MARCUS BAUMGARTNER (2024-03-07)

Part #	Whse	Description	Bin	Qty	BO	Shipped	Each	Extended
28334-001	SAV	STEER MOTOR FASTENER KIT	16B1	1	0	1	92.55	92.55
Estimated Inbound Freight								35.00
Labor								417.90

Need to place a service call?

Please visit our website www.liftpower.com, click on service request, fill out the form and click submit. The next available service technician will be dispatched to you.

Receivables sent to collections will be subject to additional costs associated with collection of a debt over and above the original debt amount.

Sub Total	\$545.45
Tax	\$8.93
Total	\$554.38