

**SHIP8, INC.**

ATTN: ACCOUNTS PAYABLE  
45875 NORTHPORT LOOP EAST  
FREMONT, CA 94538  
US

AP.SHIP8@SHIP8.COM

PO No.

24030285

PO Date

03/13/2024

Page

1 OF 1

**ORDER FROM**

1069

LIFT POWER INC.

JACKSONVILLE, FL 32254

**SHIP TO**

SD3(3000),  
SHIP8, INC.  
ATTN: CHRISTINE JENKINS  
311 INTERNATIONAL TRADE PARKWAY  
PORT WENTWORTH, GA 31407  
US

**Buyer**

Purchasing Dept

**Terms**

Net 30 Days

**FOB**

FOB Origin

**Ship Via**

Best possible

**Extended Price**

**Unit Price**

**UOM**

**Qty Ordered**

**Vendor Item Description**

**Vendor Item No.**

**Line No.**

Line No.	Vendor Item No.	Vendor Item Description	Qty Ordered	UOM	Unit Price	Extended Price
1	078723-001	CONNECTOR HOUSING GRAY 350	1.00	Each	12.77	
						3-13
2	363124-001	Battery Cleaner Can	1.00	Each	8.61	
						3-13
3	363125-001	Battery Protector Can	1.00	Each	12.30	
						3-13
4	EQU021	LABOR	1.00	Each	348.25	
						3-13

Total Extended Price =





**Industrial Trucks • Materials Handling Equipment**  
 301 Suemac Place  
 Jacksonville, FL 32254  
 (904) 783-0250 | Fax (904) 781-1451

Order # 340095319  
 Reference # 347050326  
 Open Date 3/12/2024  
 Terms - Net 30  
 Writer: Marcus B

## Road Service Order

Salesman: House CSSR

ILL  
 O: 7253  
 SHIP8 INC  
 45875 NORTHPORT LOOP EAST  
 Fremont, CA 94538  
 510-490-9788

SHIP  
 TO: 7255  
 SHIP8 INC  
 SD3  
 311 INTERNATIONAL TRADE PKWY  
 Savannah, GA 31407  
 510-490-9788

Q #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
			CROWN	PE4500-60	10173937	EPJ22	1833

Battery connector / battery cables / battery // Tech req Marcus B

WORK PERFORMED: Pm'd truck. Found and fixed following faults. 1) battery filled with excessive corrosion. Cleaned, and applied protectant to slow occurrence. 2) battery cables have exposed copper, risking shorting. Applied heat shrink and repaired. 3) sb350 melted allowing connectors to come out. replaced. Tested and returned to service service.  
 Marcus Baumgartner (2024-03-12)

Part #	Whse	Description	Bin	Qty	BO	Shipped	Each	Extended
78723-001	V3212	CONNECTOR HOUSING GRAY ...	B3	1	0	1	12.77	12.77
53124-001	V3212	BATTERY CLEANER CAN	S2	1	0	1	8.61	8.61
53125-001	V3212	BATTERY PROTECTOR CAN	S2	1	0	1	12.30	12.30
								348.25

Need to place a service call?

Please visit our website [www.liftpower.com](http://www.liftpower.com), click on service request, fill out the form and click submit. The next available service technician will be dispatched to you.

Payments sent to collections will be subject to additional costs associated with collection of a debt over and above the original debt amount.

Sub Total	<b>\$381.93</b>
Tax	<b>\$2.36</b>
Total	<b>\$384.29</b>



Search in mail



- Compose
- Mail
- Inbox
- Starred
- Snoozed
- Sent
- Drafts
- More

Labels

316

### PO Request for Lift Power - SD3 - 340095319

Inbox



**James Burford**

Christine, Please create a PO for the attached. James Burford Regional Facilities Director 311 International Trade Pkwy Port



**Christine Jenkins**

PO 24630285 attached Christine Jenkins Purchasing Coordinator 550 Northport Parkway Port Wentworth, GA 31407 O:912:



**James Burford**

to me, SAV.maint.management

PO Complete



**SHIP8 INC.**

James Burford  
Regional Facilities Director  
311 International Trade Pkwy  
Port Wentworth, GA 31407

C:912.507.7881

- Reply
- Reply all
- Forward



**Industrial Trucks • Materials Handling Equipment**  
 801 Suemac Place  
 Jacksonville, FL 32254  
 (904) 783-0250 | Fax (904) 781-1451

Inv # 340095319  
 Reference # 347050326  
 Inv Date 3/13/2024  
 Terms - Net 30  
 Writer: Marcus B

## Road Service Invoice

Salesman: House CSSR

CALL TO: 7253  
 SHIP8 INC  
 45875 NORTHPORT LOOP EAST  
 Fremont, CA 94538  
 510-490-9788

SHIP TO: 7255  
 SHIP8 INC  
 SD3  
 311 INTERNATIONAL TRADE PKWY  
 Savannah, GA 31407  
 510-490-9788

Unit #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
1030285			CROWN	PE4500-60	10173937	EPJ22	1833

Battery connector / battery cables / battery // Tech req Marcus B

WORK PERFORMED: Pinned truck. Found and fixed following faults. 1) battery filled with excessive corrosion. Cleaned, and applied protectant to slow occurrence. 2) battery cables have exposed copper, risking shorting. Applied heat shrink and repaired. 3) sb350 melted allowing connectors to come out. Replaced. Tested and returned to service service.  
 Marcus Baumgartner (2024-03-12)

Part #	Whse	Description	Bin	Qty	BO	Shipped	Each	Extended
78723-001	V3212	CONNECTOR HOUSING GRAY ...	B3	1	0	1	12.77	12.77
53124-001	V3212	BATTERY CLEANER CAN	S2	1	0	1	8.61	8.61
53125-001	V3212	BATTERY PROTECTOR CAN	S2	1	0	1	12.30	12.30
								348.25

Need to place a service call?  
 Please visit our website [www.liftpower.com](http://www.liftpower.com), click on service request, fill out the form and click submit. The next available service technician will be dispatched to you.

Revolving charges sent to collections will be subject to additional costs associated with collection of a debt over and above the original debt amount.

Sub Total	<b>\$381.93</b>
Tax	<b>\$2.36</b>
Total	<b>\$384.29</b>