

SHIP8, INC.

ATTN: ACCOUNTS PAYABLE
45875 NORTHPORT LOOP EAST
FREMONT, CA 94538
US

AP.SHIP8@SHIP8.COM

ORDER FROM

101144

PEARCE HEATING & AIR CONDITIONING, INC.
PO BOX 1189
WINTERS, CA 95694
US

SHIP TO

WDC(4000),
SHIP8, INC.
ATTN: CHRISTINE JENKINS
221 HANSON WAY
WOODLAND, CA 95776
US

Buyer

Purchasing Dept

Terms

30 days

FOB

FOB Origin

Ship Via

Best possible

Line No.	Vendor Item No.	Vendor Item Description	Qty Ordered	UOM	Unit Price	Extended Price
1	BLD003-HVAC	BLD003-HVAC Service Call Out	1.00	Each		125.00
2	BLD003-HVAC	BLD003-HVAC Service Call Out	1.00	Each		125.00

Total Extended Price =



Search in mail



- Compose
- Inbox 355
- Starred
- Snoozed
- Sent
- Drafts
- More

Labels

Fwd: Your Invoice from Pearce Heating & Air Conditioning Inc

inbox x



James Burford

Alex, Did you get a PO already for this? James Burford Regional Facilities Director 311 International Trade Pkwy Port Wentw



Alex Gonzalez

James -- I did not. Alex Gonzalez Director of Operations 2222 East Beamer St. Woodland, CA 95776 O:530.669.5991 x 116 (



Christine Jenkins

Alex Do you need a PO and was the work completed? Was this an emergency service call? Christine Jenkins Purchasing Co



Alex Gonzalez

to me, James

Work was complete and yes emergency call out.



SHIP8 INC.


Alex Gonzalez
Director of Operations
2222 East Beamer St.
Woodland, CA 95776

O:530.669.5991 x 116 C:916.897.7622

6-6-24
AJ

- Ok, thanks.
- Yes, it was.
- Yes, it was!

- Reply
- Reply all
- Forward



Pearce Heating & Air Conditioning, Inc.
 PO BOX 1199, Winters, CA 95694 United States
 (530) 795-4300

BILL TO

Ship 8 Inc.
 2222 East Beamer Street
 Woodland, CA 95776 USA

INVOICE 47647763	INVOICE DATE Jun 04, 2024
----------------------------	-------------------------------------

JOB ADDRESS

Ship 8 Inc.
 2222 East Beamer Street
 Woodland, CA 95776 USA

Completed Date:
Payment Term: Due Upon Receipt

DESCRIPTION OF WORK

Hanson Break Room 1- Found blower motor seized up. Motor will need to be replaced. Also recommend getting blower wheel cleaned and evap coil cleaned when we do the replacement
 System is also from 1997 and uses old, and restricted refrigerant. Possibly look at replacing
 Beamer Break Room 1 RTU11- Found nob for thermostat was upside down so the desired input was different then the actual input. Rotated knob and system is now operating properly
 Beamer Lobby unit RTU10- Edward mentioned issue with this unit, there is definitely an issue, did not have time today to diagnose

TASK	DESCRIPTION	QTY	PRICE	TOTAL
Commercial Diagnostic	Provided a professional consultation to determine the customer's needs/concerns and/or solutions.	1.00	\$125.00	\$125.00
Commercial Diagnostic	Provided a professional consultation to determine the customer's needs/concerns and/or solutions.	1.00	\$125.00	\$125.00

SUB-TOTAL \$250.00

TAX \$0.00

TOTAL DUE \$250.00

BALANCE DUE \$250.00

Thank you for choosing Pearce Heating & Air Conditioning, Inc.

This invoice is agreed and acknowledged. Payment is due upon receipt. A service fee will be charged for any returned checks, and a financing charge of 1% per month shall be applied for overdue amounts.

Job #47647763

Diagnostic Report (Beamer_Break_Room_1)

Customer Name

Ship 8 Inc.

Technician




Tyler P.

Date

2024-06-04

Reason For Call

System not shutting off

Data Plate

Make

Manufacturer of the unit.

Trane

Model/Product Number

Model/Product number of the unit.

YCD049C3LCBB-

Serial Number

Serial Number of the unit.

M12102307D

Manufactured/Installed Date

Manufactured/Installed date of the unit.

1997

Type of Unit


Type of Unit

Package Unit

Type of Unit: Other

Type of unit if you chose other.

-

Picture of Blower Motor

Picture of Indoor Coil

Picture of Filter

Description of Findings

Found nob for thermostat was upside down so the desired input was different then the actual

Repair Status:

Repair completed.

Customers Expectations

What are the customers expectations of next steps if any are needed

If problem persist, please call office to schedule follow up

Additional Pictures

Job #47647763

Diagnostic Report (Hanson_Break_room_1)

Customer Name

Ship 8 Inc.

Technician

Tyler P.



Date

2024-06-04

Reason For Call

System making weird humming sound

Data Plate



Make

Manufacturer of the unit.

Trane

Model/Product Number

Model/Product number of the unit.

YCD037C3LBBE

Serial Number

Serial Number of the unit.

M12103135D

Manufactured/Installed Date

Manufactured/Installed date of the unit.

03/1997

Type of Unit

Type of Unit


Package Unit

Type of Unit: Other


Type of unit if you chose other.

R-22


Picture of Blower Motor



Picture of Indoor Coil



Picture of Filter



Description of Findings

Found blower motor seized up. Motor will need to be replaced. Also recommend getting blower

Repair Status:

Office needs to order part.

Customers Expectations

What are the customers expectations of next steps if any are needed

Office will schedule follow up once we have ordered part

Additional Pictures