

SHIP8, INC.

ATTN: ACCOUNTS PAYABLE
45875 NORTHPORT LOOP EAST
FREMONT, CA 94538
US

AP.SHIP8@SHIP8.COM

ORDER FROM

1069

LIFT POWER INC.

JACKSONVILLE, FL 32254

SHIP TO

SD2(2000),
SHIP8, INC.
ATTN: CHRISTINE JENKINS
550 NORTHPORT PARKWAY
PORT WENTWORTH, GA 31407
US

PO No.

24060706

PO Date

06/24/2024

Page

1 OF 1

Buyer

Purchasing Dept

Terms

Net 30 Days

FOB

FOB Origin

Ship Via

Best possible

Extended Price

Line No.

Vendor Item No.

Vendor Item Description

Qty Ordered

UOM

Unit Price

Extended Price

1

IN35-917A-E

Strobe - Amber

6-24

1.00

Each

54.58

2

EQU021

LABOR

6-24

1.00

Each

278.60

Total Extended Price =



Search mail



- 99+
- Compose
- Mail
- Inbox
- Starred
- Chat
- Snoozed
- Meet
- Sent
- Drafts
- More

Labels

378

PO Request for SD2 - Lift Power - 340097936

Inbox x



James Burford

Christine, Please create a PO for the attached. James Burford Regional Facilities Director 311 International Trade Pkwy Port



Christine Jenkins

PO 24060706 is attached



James Burford

to me, SAV.maint.management

PO is completed.

6-24-24



SHIP8 INC.

James Burford
Regional Facilities Director
311 International Trade Pkwy
Port Wentworth, GA 31407

C:912.507.7881

- Thank you.
- Order received, thank you.
- I will get this scheduled.

- Reply
- Reply all
- Forward

LIFTPOWER

Industrial Trucks • Materials Handling Equipment

101 Suemac Place
Jacksonville, FL 32254
(904) 783-0250 | Fax (904) 781-1451

Inv # 340097936
Reference # 347052488
Inv Date 6/18/2024
Terms - Net 30
Writer: CHRIS RO

Road Service Invoice

Salesman:

BILL TO:
7253
SHIP8 INC
45875 NORTHPORT LOOP EAST
Fremont, CA 94538
510-490-9788

SHIP TO:
7256
SHIP8 INC
SD2
550 NORTHPORT PKWY
Savannah, GA 31407
510-490-9788

Unit #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
23040398			GENIE	G5-1930	GS3006B-78655		642

ITEM FOLLOW UP - Strobe light bulbs need to be replaced//NTE 500//Cust Rqst: Chris R

WORK PERFORMED: Here to take necessary photos to give to parts for strobe lights & to sign whatever wo I need to be signed
Chris Rodriguez (2024-06-12)
Arrived at location. Gate was closed but gate was about to open in 10 minutes. Gate opened, went inside to get lift. Located lift. Replaced strobe assembly,
still not working. Trying to figure out why. Noticed no power was being transferred to strobe light. Checked for fuses. Checked relay & main hub. Tied new
wires to relay with power and ground. Handed back to maintenance.
Chris Rodriguez (2024-06-13)

Part #	Whse	Description	Bin	Qty	BO	Shipped	Each	Extended
135-917A-E	SAV	STROBE - AMBER	12C	1	0	1	54.58	54.58
								278.60

Need to place a service call?
Please visit our website www.liftpower.com, click on service request, fill out the form and click submit. The next available service technician will be
dispatched to you.

Service invoices sent to collections will be subject to additional costs associated with collection of a debt over and above the original debt amount.

Sub Total: **\$333.18**
Tax: **\$3.82**
Total: **\$337.00**