

SHIP8, INC.

ATTN: ACCOUNTS PAYABLE
 45875 NORTHPORT LOOP EAST
 FREMONT, CA 94538

AP.SHIP8@SHIP8.COM

ORDER FROM

1069

LIFT POWER INC.

JACKSONVILLE, FL 32254

SHIP TO

SD3(3000),
 SHIP8, INC.
 ATTN: CHRISTINE JENKINS
 311 INTERNATIONAL TRADE PARKWAY
 PORT WENTWORTH, GA 31407
 US

Buyer Purchasing Dept Net 30 Days Terms FOB Ship Via Best possible

Line No.	Vendor Item No.	Vendor Item Description	Qty Ordered	UOM	Unit Price	Extended Price
1	077145	Filter Element	1.00	Each	12.46	12.46
2	122910	Tray Drip	1.00	Each	89.61	89.61
3	118913	Brush Set	1.00	Each	110.98	110.98
4	101582	Brush Stone & Holder Set	1.00	Each	98.88	98.88
5	EQU021	FLAT RATE LABOR	1.00	Each	626.85	626.85

7-29

Total Extended Price =

LIFTPOWER

Industrial Trucks • Materials Handling Equipment
 6801 Suemac Place
 Jacksonville, FL 32254
 (904) 783-0250 Fax (904) 781-1451

Quote # 934005467
 Reference # 340098526
 Quote Date 7/12/2024
 Terms - Net 30

Road Service Quote

Salesman: House CSSR

Writer:

BILL TO: 7253
 SHIP8 INC
 45875 NORTHPORT LOOP EAST
 Fremont, CA 94538
 510-490-9788

SHIP TO: 7255
 SHIP8 INC
 SD3
 311 INTERNATIONAL TRADE PKWY
 Savannah, GA 31407
 510-490-9788

PO #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
			CROWN	SP3520-30	1A356063	OP24	8515

Quote to replace drip pan / pump motor brushes / and hyd. oil filter

Work completed on 340098526

Contact James Burford
 james.burford@ship8.com

Part #	Whse	Description	Bin	Qty	Each	Extended
077145	V3174	FILTER ELEMENT	E4	1	12.46	12.46
122910	SAV	TRAY DRIP	New	1 NA	89.61	89.61
118913	SAV	BRUSH SET	16G1	1	110.98	110.98
101582	SAV	BRUSH STONE & HOLDER SET	25C3	1	98.88	98.88
Labor						626.85

Quote

This Quotation is valid for 30 days.
 This Quotation is subject to +/- 10% variation based on cost (Freight is only an estimate).
 Any Additional work found will be quoted for customer approval.

Sub Total	\$938.78
Tax	\$21.84
Total	\$960.62

James Burford
To: Christine Jenkins

This is completed.



SHIP8 INC.

James Burford
Regional Facilities Director
311 International Trade Pkwy
Port Wentworth, GA 31407

C:912.507.7881

#358K

Reply Forward

You



PO:2470848 is attached Christine Jenkins Purchasing Coordinator 550 Northport Parkway Port Wentworth, GA 31407 O:912-373-7778 X:3751

From: James Burford <james.burford@...> Mon 7/29/2024 12:48 PM

James Burford

To: Christine Jenkins

I am thinking, since it is setup in EEC as SD3. Then P&L wise I think it would be on SD3... But I am not sure.



SHIP8 INC

James Burford
Regional Facilities Director
311 International Trade Pkwy
Port Wentworth, GA 31407

C:912.507.7881

You

James PO 24070848 was for SD3 but they have the invoice under SD2 Christine Jenkins Purchasing Coordinator 550 Northport Parkway Port Wentworth, GA 31407 0:912-373-7778 X:3751

Wed 7/31/2024 7:24 AM

LIFTPOWER

Industrial Trucks • Materials Handling Equipment

301 Suemac Place
Jacksonville, FL 32254
(904) 783-0250 | Fax (904) 781-1451

Inv # 340098526
Reference # 934005467
Inv Date 7/29/2024
Terms - Net 30
Writer:

Road Service Invoice

Salesman: House CSSR

BILL TO:
7253
SHIP8 INC
45875 NORTHPORT LOOP EAST
Fremont, CA 94538
510-490-9788

SHIP TO:
7256
SHIP8 INC
SD2
550 NORTHPORT PKWY
Savannah, GA 31407
510-490-9788

Q #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
1070848			CROWN	SP3520-30	1A356063	OP24	8515

oil smell / Brushes need inspecting - may have oil on them // pump does not sound right / oil on bottom of the motor where fins are // Customer req Eric A.

WORK PERFORMED: Inspected and tested found oil leaking from hyd filter. Was tight, tightened more, still leaks during operation. Replaced oil filter will place brushes and clean motor, and order missing drip plate to prevent this happening again. Customer has removed drip plates from all their trucks, will commend they replace them. Again.

(Marcus Baumgartner (2024-06-28))

researched and ordered parts. Picked up parts. Returned to site. Accessed lift. Uninstalled brushes. Cleaned motor as much as possible with contact cleaner. Installed new brushes. Stoned motor. Reinstalled motor. Tested. Will return to install drip plate when parts come in.

(Marcus Baumgartner (2024-07-01))

Picked up parts, and returned to site. Located, moved to work area. Installed drip plate. Motor does still make an excessive noise, but operates properly, will likely continue to make noise due to wear to armature. Tested and returned to service.

(Marcus Baumgartner (2024-07-11))

Part #	Whse	Description	Bin	Qty	BO	Shipped	Each	Extended
77145	V3174	FILTER ELEMENT	E4	1	0	1	12.46	12.46
22910	SAV	TRAY DRIP	New	1	0	1	89.61	89.61
18913	SAV	BRUSH SET	16G1	1	0	1	110.98	110.98
21582	SAV	BRUSH STONE & HOLDER SET	25C3	1	0	1	98.88	98.88
								626.85

Need to place a service call?

Please visit our website www.liftpower.com, click on service request, fill out the form and click submit. The next available service technician will be dispatched to you.

voices sent to collections will be subject to additional costs associated with collection of a debt over and above the original debt amount.

Sub Total	\$938.78
Tax	\$21.84
Total	\$960.62