

RE: Fire Alarm/Riser issue - important

From Timothy Rodgers [TX-DAL] <trodgers@SummitFireSecurity.com>

Date Mon 5/12/2025 2:12 PM

To James Burford <james.burford@ship8.com>; Larry Gifford [TX-DAL] <LGifford@SummitFireSecurity.com>; Robert Harvey [TX-DAL] <RHarvey@SummitFireSecurity.com>

Cc Nancy Hattersley <nancy.hattersley@jlahome.com>; John Poole <John.poole@nfiindustries.com>

Very strange, I don't see how it could be from the sprinkler.

Labor- \$465
FIKM500M- \$131.25
Trip Charge- \$85

Assuming only one module needs to be replaced, we can complete the repair for 681.25+tax



Timothy Rodgers
Fire Alarm & Security Manager
D 817-854-8476
C 817-480-1077
1203 S. 2nd Avenue
Mansfield, TX 76063
Office: 817-842-1220
www.summitfiresecurity.com

This is a commercial email sent by Summit Companies or one of its affiliates, with an office located at 1250 Northland Drive, Suite 200, Mendota Heights, MN 55120. If you no longer wish to receive commercial emails from Summit Companies, please let us know by contacting us by mail or by email at privacy@summitcompanies.com to opt out.

IMPORTANT: Information contained in this e-mail may be privileged, confidential, and subject to other protections, including, but not limited to, the Electronic Communications Privacy Act, 18 U.S.C. Sections 2510-2521. If you are not the intended recipient, do not read, distribute, or reproduce this transmission. If you have received this e-mail in error, please notify the sender immediately and delete the message from your system. Thank you for your cooperation.

From: James Burford <james.burford@ship8.com>

Sent: Monday, May 12, 2025 11:25 AM

To: Larry Gifford [TX-DAL] <LGifford@SummitFireSecurity.com>; Robert Harvey [TX-DAL] <RHarvey@SummitFireSecurity.com>; Timothy Rodgers [TX-DAL] <trodgers@SummitFireSecurity.com>

Cc: Nancy Hattersley <nancy.hattersley@jlahome.com>; John Poole <John.poole@nfiindustries.com>

Subject: Fw: Fire Alarm/Riser issue - important

CAUTION: This email originated from outside the organization. Do not follow guidance, click links, or open attachments unless you **KNOW** the content is safe.

Larry/Robert/Tim - Can someone send me an estimate on how much it would cost for this to be looked at and repaired? It is odd how there is water splash on the wall there, but nothing above it. Please look to see if there was any possible way this could have been caused by the fire sprinkler system.

James Burford
Regional Facilities Director
311 International Trade Pkwy
Port Wentworth, GA 31407

C:912.507.7881

From: Poole, John <john.poole@nfiindustries.com>

Sent: Monday, May 12, 2025 8:45 AM

To: James Burford <james.burford@ship8.com>

Subject: Fire Alarm/Riser issue - important

James - the alarm was given the following troubled condition that i never saw before. When i went to check out Riser 9, which is what was reference in the fault indicator, i saw a potential pipe or roof water leak that is hitting the panel and sensors (?) which might be the cause but am unsure. See photos.

Site 1 Panel 1
FIRE TROUBLE: Waterflow Sw
RISER 9 WATERFLOW
05/11/25 01:21:04AM [Z012][M97:M047]

ALARM

SUPERVISORY

TROUBLE

SILENCED

POWER





SP-4

FIRE SWITCH
Alarms

CAUTION

R This box contains Approved Automatic Fire Suppressors and Wrench
For Emergency Use

AUXILIARY
DRAIN
SYSTEM
9

CHILLOTTE PIPE