

PURCHASE ORDER



E&E CO., LTD.

45875 NORTHPORT LOOP EAST

FREMONT, CA 94538

UNITED STATES

PO No.	PO Date	Page
24010078	01/24/2024	1 OF 2

ORDER FROM

6526

JK&K INC DBA BACKFLOW PREVENTER TEST & REPAIR
SVC
2616 HANDLEY DRIVE
FORT WORTH, TX 76112
US

SHIP TO

ZAGAM(7800),
ZAGAM LLC
ATTN: JAMES BURFORD
2101 MILLERS FERRY ROAD
WILMER, TX 75125
US

Buyer	Terms	FOB	Ship Via
Purchasing Dept	30 days	FOB Origin	Best possible

Line No.	Vendor Item No.	Vendor Item Description	Qty Ordered	UOM	Unit Price	Extended Price
1	Repair - BFP	BACKFLOW DEVICE REPAIRS - #TK1926 #1 Check Failed	1.00	Each	0.00	0.00
2	Parts - BFP	BACKFLOW PARTS - Check 1 Replacement	1.00	Each	425.00	425.00
3	Labor - BFP	LABOR and retest after repairs	2.00	Each	75.00	150.00
4	Repair - RPZ	REPAIRS/RPZ - #VG0656 watts 3" 957	1.00	Each	0.00	0.00
5	Parts - BFP	Backflow Parts - Check 1	1.00	Each	460.00	460.00
6	Parts - BFP	Backflow Parts - Check 2	1.00	Each	420.00	420.00

PURCHASE ORDER



E&E CO., LTD.

45875 NORTHPORT LOOP EAST

FREMONT, CA 94538

UNITED STATES

PO No.

24010078

PO Date

01/24/2024

Page

2 OF 2

ORDER FROM

6526

JK&K INC DBA BACKFLOW PREVENTER TEST & REPAIR
SVC
2616 HANDLEY DRIVE
FORT WORTH, TX 76112
US

SHIP TO

ZAGAM(7800),
ZAGAM LLC
ATTN: JAMES BURFORD
2101 MILLERS FERRY ROAD
WILMER, TX 75125
US

Buyer

Purchasing Dept

Terms

30 days

FOB

FOB Origin

Ship Via

Best possible

Line No.	Vendor Item No.	Vendor Item Description	Qty Ordered	UOM	Unit Price	Extended Price
7	Parts - RP Assembly	RPZ Complete kit	1.00	Each	1,000.00	1,000.00
8	Labor - BFP	LABOR and retest after repairs	2.00	Each	75.00	150.00
9	City Fee	City of Wilmer Fee	2.00	Each	15.00	30.00
10	MSCNOTES	MISC NOTES: REFERENCE ESTIMATE 1164, DATED 01/23/2024,	1.00	Each	0.00	0.00

Total Extended Price =

2,635.00



- E&E
- JLA
- SYNC
- HH

Requisition #: _____
 Requester: James Burford
 Department: _____
 Date: 1/24/2024
 Order #: _____

VENDOR/SUPPLIER	
Business	DAX Backflow Preventer Test and Repair Services
Contact	
Address	
Address 2	
Telephone #	
Fax #	

SHIP TO
Zagam
2101 Millers Ferry Road
Wilmer, TX 75125
510-490-9788 x127

Item	Description	Unit Price	Quantity	Sub-Total	Remarks/Purpose	Coding
	Backflow Repair			\$ -	Proposal # 1164	
Repair - BFP	BACKFLOW DEVICE REPAIRS - #TK1926 #1 Check Failed	\$ -	1.00	\$ -		
Parts - BFP	BACKFLOW PARTS - Check 1 Replacement	\$ 425.00	1.00	\$ 425.00		
Labor - BFP	LABOR and retest after repairs	\$ 75.00	2.00	\$ 150.00		
				\$ -		
Repair - RPZ	REPAIRS/RPZ - #VG0656 watts 3' 957	\$ -	1.00	\$ -		
Parts - BFP	Backflow Parts - Check 1	\$ 460.00	1.00	\$ 460.00		
Parts - BFP	Backflow Parts - Check 2	\$ 420.00	1.00	\$ 420.00		
Parts - RP Assembly	RPZ Complete kit	\$1,000.00	1.00	\$ 1,000.00		
Labor - BFP	LABOR and retest after repairs	\$ 75.00	2.00	\$ 150.00		
				\$ -		
City Fee	City of Wilmer Fee	\$ 15.00	2.00	\$ 30.00		
				\$ -		
				\$ -		

DO NOT PLACE AN ORDER WITHOUT APPROVAL

Estimated Total **\$ 2,635.00**

Requester's Signature: James Burford
 Direct Manager's Approval: _____
 Dept Manager's Approval: _____
 Add'l Authorizer (over 2K): _____
 Add'l Authorizer (over 1K): _____
 IT Authorizer (Computer soft & hardware): _____

Date: 1/24/2024
 Date: _____
 Date: _____
 Date: _____
 Date: _____
 Date: _____

Administration Use Only

Order Date: _____ Ordered by: _____
 Est. Delivery Date: _____ Ordered Amount: _____
 Payment Method: (Please check one)

- Open Account (Vendor bill) Provide REQ# to vendor for invoicing, submit approved requisition form to A/P for payment processing
- COD/Prepaid Submit approved requisition form and vendor invoice to Controller for COD/prepaid check
- Company Credit Card Submit approved requisition form and receipt to Credit Card Holder
- Employee Credit Card/Check Attach approved requisition form and receipt to employee's expense report for reimbursement

Backflow Preventer Test and Repair Services

2616 HANDLEY DR.
FORT WORTH, TX 76112 US
817-705-0237
office@daxbackflowtesting.com

ADDRESS
Zagam LLC
2101 millers ferry road
Wilmer, TX 75172

SHIP TO
Zagam LLC
2101 millers ferry road
Wilmer, TX 75172

Estimate 1164

DATE 01/23/2024

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
REPAIR - BFP	BACKFLOW DEVICE REPAIRS #TK1926 #1 check failed	1	0.00	0.00T
PARTS - BFP	BACKFLOW PARTS check 1 replacement	1	425.00	425.00T
LABOR - BFP	LABOR and retest after repairs	2	75.00	150.00T
REPAIR - RPZ	REPAIRS/RPZ #VG0656 watts 3" 957	1	0.00	0.00T
PARTS - BFP	BACKFLOW PARTS check 1	1	460.00	460.00T
PARTS - BFP	check 2	1	420.00	420.00T
PARTS - RP ASSEMBLY	RPZ complete kit	1	1,000.00	1,000.00T
LABOR - BFP	LABOR retest after repair	2	75.00	150.00T
City Fee	City Fee wilmer fee not ours	2	15.00	30.00

SUBTOTAL 2,635.00
TAX 214.91

TOTAL \$2,849.91

Accepted By

Accepted Date