

PURCHASE ORDER

SHIP8, INC.

ATTN: ACCOUNTS PAYABLE
 45875 NORTHPORT LOOP EAST
 FREMONT, CA 94538
 US
 AP.SHIP8@SHIP8.COM

PO No. 24020114

PO Date 02/01/2024

Page 1 OF 2

SHIP TO

SD3(3000),
 SHIP8, INC.
 ATTN: CHRISTINE JENKINS
 311 INTERNATIONAL TRADE PARKWAY
 PORT WENTWORTH, GA 31407
 US

ORDER FROM

1069
 LIFT POWER INC.
 JACKSONVILLE, FL 32254

Buyer Purchasing Dept Terms Net 30 Days FOB FOB Origin Ship Via Best possible

Line No.	Vendor Item No.	Vendor Item Description	Qty Ordered	UOM	Unit Price	Extended Price
1	115033-302-88	WHEEL ASM 5x4.12x2.44x0.83	1.00	Each	77.13	77.13
2	073962-003	AXLE	1.00	Each	42.49	42.49
3	060000-030	PIN ROLL	4.00	Each	0.45	1.80
4	060030-127	FLATWASHER	4.00	Each	1.03	4.12
5	060030-278	FLATWASHER	4.00	Each	5.39	21.56
6	060030-093	FLATWASHER	4.00	Each	0.63	2.52

2-1-24



PURCHASE ORDER

SHIP8, INC.

ATTN: ACCOUNTS PAYABLE
 45875 NORTHPORT LOOP EAST
 FREMONT, CA 94538
 US
 AP.SHIP8@SHIP8.COM

PO No. 24020114 PO Date 02/01/2024 Page 2 OF 2

ORDER FROM

1069

LIFT POWER INC.

JACKSONVILLE, FL 32254

SHIP TO

SD3(3000),
 SHIP8, INC.
 ATTN: CHRISTINE JENKINS
 311 INTERNATIONAL TRADE PARKWAY
 PORT WENTWORTH, GA 31407
 US

Buyer

Purchasing Dept

Terms

Net 30 Days

FOB

FOB Origin

Ship Via

Best possible

Line No.	Vendor Item No.	Vendor Item Description	Qty Ordered	UOM	Unit Price	Extended Price
7	111858-002	SLEEVE	4.00	Each	11.81	47.24
8	065084-015	BEARING	4.00	Each	7.74	30.96
9	076048-001	FITTING LUBRICATION	1.00	Each	0.73	0.73
10	EQU021	LABOR	1.00	Each	255.00	255.00

Total Extended Price = 483.55

LIFTPOWER

Industrial Trucks • Materials Handling Equipment
 6801 Suemac Place
 Jacksonville, FL 32254
 (904) 783-0250 | Fax (904) 781-3451

Order # 340094029

Open Date 1/26/2024
 Terms - Net 30

Road Service Order

Salesman: House GSSR

Writer:

BILL TO:

7253
 SHIP8 INC
 45875 NORTHPORT LOOP EAST
 Fremont, CA 94538
 510-490-9788

SHIP TO:

7255
 SHIP8 INC
 SD3
 311 INTERNATIONAL TRADE PKWY
 Savannah, GA 31407
 510-490-9788

PO #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
			CROWN	RR5275S-45	1A334267	R1858	16281

No travel / Load wheel ASM is coming apart // Tech req Marcus B

WORK PERFORMED: Accessed lift, inspected, and tested. Found load wheel ASM coming apart due to broken roll pin and also found no travel. Troubleshoot and found foot pedal switch not triggering. Found switch operable, but loose connection in connector was keeping truck from seeing input. Repaired and problem was fixed. Also found load wheel ASM coming apart. Disassembled, located missing parts, and found that axle needs replacement. Returned to shop, picked up parts, the returned to site, repaired, and reassembled. Tested and returned to service. Marcus Baumgartner (2024-01-29)

Part #	Whse	Description	Bin	Qty	BO	Shipped	Each	Extended
115033-301-88	SAV	WHEEL ASM 5x4.12x2.44x0.63	32D	1	0	1	77.13	77.13
073962-003	SAV	AXLE	T8C2	1	0	1	42.49	42.49
060000-030	SAV	PIN ROLL	16A1	4	0	4	0.45	1.80
060030-127	SAV	FLATWASHER	18A6	4	0	4	1.03	4.12
060030-278	SAV	FLATWASHER	15D5	4	0	4	5.39	21.56
060030-093	SAV	FLATWASHER	15A1	4	0	4	0.63	2.52
111858-002	SAV	SLEEVE	15B3	4	0	4	11.81	47.24
065084-015	SAV	BEARING	15A4	4	0	4	7.74	30.96
076048-001	SAV	FITTING LUBRICATION	16B5	1	0	1	0.73	0.73
Flat Rate Labor:								255.00

Need to place a service call?

Please visit our website www.liftpower.com, click on service request, fill out the form and click submit. The next available service technician will be dispatched to you.

Invoices sent to collections will be subject to additional costs associated with collection of a debt over and above the original debt amount.

Sub Total	\$483.55
Tax	\$16.00
Total	\$499.55



Search in mail



99+

Compose

Mail

Inbox

276

PO Request for Lift Power - SD3 - Quote # 340094029

Inbox x



James Burford

Christine, Please create a PO for the attached. James Burford Regional Facilities Director 311 International Trade Pkwy Port



Christine Jenkins

PO 24020114 attached Christine Jenkins Purchasing Coordinator 550 Northport Parkway Port Wentworth, GA 31407 O:912.:



James Burford

to me, SAV.maint.management

Thanks - This PO is completed.



SHIP8 INC.

James Burford
Regional Facilities Director
311 International Trade Pkwy
Port Wentworth, GA 31407

C:912.507.7881

- Thank you.
- Order received, thank you.
- Got it, thank you.

- Reply
- Reply all
- Forward

Chat

Starred

Snoozed

Meet

Sent

Drafts

More

Labels

LIFTPOWER

Industrial Trucks • Materials Handling Equipment
 6801 Suemac Place
 Jacksonville, FL 32254
 (904) 783-0250 | Fax (904) 781-1451

Inv # 340094029

Inv Date 2/1/2024

Terms - Net 30

Road Service Invoice

Salesman: House CSSR

Writer:

BILL TO: 7253
 SHIP8 INC
 45875 NORTHPORT LOOP EAST
 Fremont, CA 94538
 510-490-9788

SHIP TO: 7255
 SHIP8 INC
 SD3
 311 INTERNATIONAL TRADE PKWY
 Savannah, GA 31407
 510-490-9788

PO #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
24020114			CROWN	RR5275S-45	1A334267	R1858	16281

No travel / Load wheel ASM is coming apart // Tech req Marcus B

WORK PERFORMED: Accessed lift, inspected, and tested. Found load wheel ASM coming apart due to broken roll pin and also found no travel. Troubleshoot and found foot pedal switch not triggering. Found switch operable, but loose connection in connector was keeping truck from seeing input. Repaired and problem was fixed. Also found load wheel ASM coming apart. Disassembled, located missing parts, and found that axle needs replacement. Returned to shop, picked up parts, the returned to site, repaired, and reassembled. Tested and returned to service. Marcus Baumgartner (2024-01-29)

Part #	Whse	Description	Bin	Qty	BO	Shipped	Each	Extended
115033-301-88	SAV	WHEEL ASM 5x4.12x2.44x0.83	32D	1	0	1	77.13	77.13
073962-003	SAV	AXLE	18C2	1	0	1	42.49	42.49
060000-030	SAV	PIN ROLL	16A1	4	0	4	0.45	1.80
060030-127	SAV	FLATWASHER	18A6	4	0	4	1.03	4.12
060030-278	SAV	FLATWASHER	15D5	4	0	4	5.39	21.56
060030-093	SAV	FLATWASHER	15A1	4	0	4	0.63	2.52
111858-002	SAV	SLEEVE	15B3	4	0	4	11.81	47.24
065084-015	SAV	BEARING	15A4	4	0	4	7.74	30.96
076048-001	SAV	FITTING LUBRICATION	16B5	1	0	1	0.73	0.73
Flat Rate Labor								255.00

Need to place a service call?

Please visit our website www.liftpower.com, click on service request, fill out the form and click submit. The next available service technician will be dispatched to you.

Invoices sent to collections will be subject to additional costs associated with collection of a debt over and above the original debt amount.

Sub Total	\$483.55
Tax	\$16.00
Total	\$499.55