

**SHIP8, INC.**

ATTN: ACCOUNTS PAYABLE  
 45875 NORTHPORT LOOP EAST  
 FREMONT, CA 94538

US

AP.SHIP8@SHIP8.COM

**ORDER FROM**

1069

LIFT POWER INC.

JACKSONVILLE, FL 32254

**SHIP TO**

SD3(3000),  
 SHIP8, INC.  
 ATTN: CHRISTINE JENKINS  
 311 INTERNATIONAL TRADE PARKWAY  
 PORT WENTWORTH, GA 31407  
 US

PO No. 24050553  
 PO Date 05/23/2024  
 Page 1 OF 1

Buyer Purchasing Dept Terms Net 30 Days FOB Origin Ship Via Best possible

Line No.	Vendor Item No.	Vendor Item Description	Qty Ordered	UOM	Unit Price	Extended Price
1	077145	FILTER ELEMENT	1.00	Each	12.46	
2	140963	ASM Keyless Keypresswitch	1.00	Each	104.63	
3	EQU021	LABOR	1.00	Each	278.60	

5-21  
 5-21  
 5-21

Total Extended Price =





Gmail

Search in mail



99+

Compose

Mail

Inbox

353

### PO Request for Lift Power SD3 - 340097233

Inbox x

Chat

Starred



**James Burford**

Christine, Please create a PO for the attached. James Burford Regional Facilities Director 311 International Trade Pkwy Port

Meet

Sent



**Christine Jenkins**

PO 24050553 is attached Christine Jenkins Purchasing Coordinator 550 Northport Parkway Port Wentworth, GA 31407 O:91

Drafts

More

Labels



**James Burford**

to me, SAV.maint.management

PO Completed on 5/21



**SHIP8 INC.**

James Burford  
Regional Facilities Director  
311 International Trade Pkwy  
Port Wentworth, GA 31407

C:912.507.7881

Order received, thank you.

Received, thank you.

Thank you.

Reply

Reply all

Forward

# LIFTPOWER

Industrial Trucks • Materials Handling Equipment

301 Suemac Place  
Jacksonville, FL 32254  
(904) 783-0250 | Fax (904) 781-1451

Inv # 340097233  
Reference # 347051793  
Inv Date 5/21/2024  
Terms - Net 30  
Writer: JOHN WH

## Road Service Invoice

Salesman:

**BILL TO:** 7253  
SHIP8 INC  
45875 NORTHPORT LOOP EAST  
Fremont, CA 94538  
510-490-9788

**SHIP TO:** 7255  
SHIP8 INC  
SD3  
311 INTERNATIONAL TRADE PKWY  
Savannah, GA 31407  
510-490-9788

Job #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
Job # 24050553			CROWN	SP3520-30	1A589975	OP60	940

Replace ignition switch. PMFU recommended from recent PM tech.

WORK PERFORMED: Accessed lift. Noted that hydraulic filter beyond service limit. Replaced. Uninstalled and replaced ignition switch. Tested and returned service.

Marcus Baumgartner (2024-05-21)

Part #	Whse	Description	Bin	Qty	BO	Shipped	Each	Extended
77145	V3212	FILTER ELEMENT	S1	1	0	1	12.46	12.46
40963	V3212	ASM KEYLESS KEYSWITCH	B2	1	0	1	104.63	104.63
labor								278.60

Need to place a service call?

Please visit our website [www.liftpower.com](http://www.liftpower.com), click on service request, fill out the form and click submit. The next available service technician will be dispatched to you.

voices sent to collections will be subject to additional costs associated with collection of a debt over and above the original debt amount.

Sub Total \$395.69  
Tax \$8.20  
Total \$403.89