

**SHIP8, INC.**

ATTN: ACCOUNTS PAYABLE  
45875 NORTHPORT LOOP EAST  
FREMONT, CA 94538  
US

AP.SHIP8@SHIP8.COM

**ORDER FROM**

100248

CHAMPION FIRE PROTECTON, INC.

SAVANNAH, GA 31401

**SHIP TO**

SD3(3000),  
SHIP8, INC.  
ATTN: CHRISTINE JENKINS  
311 INTERNATIONAL TRADE PARKWAY  
PORT WENTWORTH, GA 31407  
US

PO No. 24060726  
PO Date 06/26/2024

Buyer  
Purchasing Dept

Terms  
Net 30 Days

FOB  
FOB Origin

Ship Via  
Best possible

Extended Price

Line No.	Vendor Item No.	Vendor Item Description	Qty Ordered	UOM	Unit Price	Extended Price
1	BLD005-FIRE	Panel Board	1.00	Each		1,925.00

*Inv. 8-16*

Total Extended Price =



---

**Dialer Card**

1 message

---

**Charles Wood** <cwood@championfp.com>

Wed, Jun 26, 2024 at 12:37 PM

To: Patrick Andreshack <patrick.andreshack@ship8.com>, James Burford <james.burford@ship8.com>

Guys,

The cost to replace the dialer card is \$1,925.00. This includes the labor from today plus the labor to install the new dialer. I can have it here tomorrow.

Thanks,


Charles Wood, ET, GROL

Fire Alarm Service Manager

Champion Fire Protection, Inc

O-912-234-0111

C-912-663-8279



133262

0029785060

Patrick Andreshack

To: Christine Jenkins; James Burford

CC: sav.maint.management

Yes, This has been completed




**SHIP8 INC.**

Patrick Andreshack  
Maintenance Manager  
550 Northport Parkway  
Port Wentworth, GA, 31407

C: 912.414.6118

Thank you! Great, thank you so much! Thank you very much!

Reply Reply all Forward



Christine Jenkins

To: James Burford

CC: sav.maint.management

Team

Was PO 24060726 completed?

**INVOICE**

INVOICE NO

133069

Champion Fire Protection, Inc.  
825 Wheaton Street  
Savannah, GA 31401  
Phone: (912) 234-0111  
Fax: (912) 236-1303

CUST SHIP8 INC  
45875 NORTHPORT LOOP E  
FREMONT, CA 94538

SITE 311 INTERNATIONAL TRADE PKWY  
SHIP8  
PORT WENTWORTH, GA 31407

ACCOUNT NO	PO NUMBER	INVOICE DATE	TERMS	DUE DATE	PAGE
193342	24060726	8/16/2024	Net 30	9/15/2024	1

DATE COMPLETED 6/28/24  
FIRE ALARM SERVICE

Trouble shooting determined the dialer card was bad. Returned and replaced the dialer card.  
Programmed the new dialer card. All systems normal upon completion.

QUANTITY	DESCRIPTION	UNIT PRICE	EXTENDED
1	PER PROPOSAL INSTALL NEW DIALER	1925.00	1,925.00 *

\* means item is non-taxable

**TOTAL AMOUNT 1,925.00**

**Champion Fire is paperless!**  
If you would like your invoices emailed  
send request to: [ar@championfp.com](mailto:ar@championfp.com)

To request inspection reports please  
email: [swood@championfp.com](mailto:swood@championfp.com)

If you would like to be emailed a credit  
card payment link send request to:  
"[ar@championfp.com](mailto:ar@championfp.com)" with your  
invoice number. (Invoices over \$1500 are  
subject to a 3% processing fee)