

# LIFTPOWER

Industrial Trucks - Materials Handling Equipment

6801 Suemac Place

Jacksonville, FL 32254

(904) 783-0250 | Fax (904) 781-1451

Quote # 934006650

Reference # 340112903

Quote Date 8/22/2025

Terms - Net 30

Writer: TQ288302

## Road Service Quote

Salesman:

### BILL

TO: 7253  
SHIP8 INC  
45875 NORTHPORT LOOP EAST  
Fremont, CA 94538  
510-490-9788

### SHIP

TO: 7255  
SHIP8 INC  
SD3  
311 INTERNATIONAL TRADE PKWY  
Savannah, GA 31407  
510-490-9788

PO #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
			CROWN	5P3520-30	1A589977	OP62	2367

Quote to replace ECR 3.

Diagnostic time from 340112903 has been added to this quote.

QUOTES emailed to sav.mait.management@ship8.com.

Part #	Whse	Description	Bin	Qty	Each	Extended
159777-004	SAV	BEARING BALL SENSOR	22F5	1	237.30	237.30
ESTIMATED INBOUND FREIGHT						25.00
Labor						955.50

# Quote

This Quotation is valid for 30 days.

This Quotation is subject to +- 10% variation based on cost (Freight is only an estimate).

Any Additional work found will be quoted for customer approval.

Sub Total	\$1,217.80
Tax	\$18.36
Total	\$1,236.16

# LIFTPOWER

Industrial Trucks - Materials Handling Equipment

6801 Suemac Place  
Jacksonville, FL 32254  
(904) 783-0250 | Fax (904) 781-1451

Inv # 340112903

Reference # 934006650

Inv Date 9/3/2025

Terms - Net 30

## Road Service Invoice

Salesman:

Writer:

### BILL TO:

7253  
SHIP8 INC  
45875 NORTHPORT LOOP EAST  
Fremont, CA 94538  
510-490-9788

### SHIP TO:

7255  
SHIP8 INC  
SD3  
311 INTERNATIONAL TRADE PKWY  
Savannah, GA 31407  
510-490-9788

PO #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
25080923			CROWN	SP3520-30	1A589977	OP62	2374.8

Inspect & quote. Show travel. Cust req.

This time has been added to quote 934006650

POC: Patrick Andresniak, 912.414.6118

WORK PERFORMED: Checked lift and it was throw code 330 checked and found ecr 3 to be bad  
JC Kirkland (2025-08-22)

Checked lift and found loose connection repaired and ran  
JC Kirkland (2025-09-02)

Part #	Whse	Description	Bin	Extended
		Labor		441.00

Need to place a service call?

Please visit our website [www.liftpower.com](http://www.liftpower.com), click on service request, fill out the form and click submit. The next available service technician will be dispatched to you.

Invoices sent to collections will be subject to additional costs associated with collection of a debt over and above the original debt amount.

Sub Total	\$441.00
Tax	\$0.00
Total	\$441.00