

SHIP8, INC.

ATTN: ACCOUNTS PAYABLE
 45875 NORTHPORT LOOP EAST
 FREMONT, CA 94538
 US
 AP.SHIP8@SHIP8.COM

ORDER FROM
 1069

LIFT POWER INC.

JACKSONVILLE, FL 32254

SHIP TO

SD3(3000),
 SHIP8, INC.
 ATTN: CHRISTINE JENKINS
 311 INTERNATIONAL TRADE PARKWAY
 PORT WENTWORTH, GA 31407
 US

Buyer

Terms

FOB

Ship Via

Purchasing Dept

Net 30 Days

FOB Origin

Best possible

Line No.	Vendor Item No.	Vendor Item Description	Qty Ordered	UOM	Unit Price	Extended Price
1	324100-018-10	Hose-10 Feet	1.00	Each	214.73	214.73
2	141533	ENCODER BEARING 32 HALL ROT	1.00	Each	307.77	307.77
3	363504-101	HYDRAULIC OIL AW32 GALLON JUG	1.00	Each	30.40	30.40
4	MSC023-SHIPPING/FREIGHT	INBOUND FREIGHT QUOTE	1.00	Each	50.00	50.00
5	EQU021	FLAT RATE LABOR	1.00	Each	661.50	661.50

1-28 Jan

Total Extended Price =

LIFTPOWER

Industrial Trucks - Materials Handling Equipment

6801 Suemac Place
 Jacksonville, FL 32254
 (904) 783-0250 | Fax (904) 781-1451

Quote # 934007059

Reference # 340116546

Quote Date 12/16/2025

Terms - Net 30

Writer: TQ330995

Road Service Quote

Salesman:

BILL TO:	7253 SHIP8 INC 45875 NORTHPORT LOOP EAST Fremont, CA 94538 510-490-9788	SHIP TO:	7255 SHIP8 INC SD3 311 INTERNATIONAL TRADE PKWY Savannah, GA 31407 510-490-9788
-----------------	---	-----------------	--

PO #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
			CROWN	SP3520-30	1A589992	OP64	1954

Quote to replace tank to pump hose and platform height encoder.

Diagnostic time from 340116546 has been added to this quote.

Please email quote to sav.mait.management@ship8.com.

Part #	Whse	Description	Bin	Qty	Each	Extended
324100-018-10	SAV	HOSE - 10 FEET	New	1 NA	214.73	214.73
141533	SAV	ENCODER BEARING 32 HALL R...	15C1	1	307.77	307.77
363504-101	SAV	HYDRAULIC OIL AW32 GALLO...	RACK03FL	1	30.40	30.40
ESTIMATED INBOUND FREIGHT				1		50.00
Labor						661.50

Quote

This Quotation is valid for 30 days.

This Quotation is subject to +/- 10% variation based on cost (Freight is only an estimate).

Any Additional work found will be quoted for customer approval.

Sub Total	\$1,264.40
Tax	\$42.20
Total	\$1,306.60









12192025-SD3- 934007059-Adobe


Final Audit Report

2025-12-20

Created:	2025-12-19
By:	Angele White (angele.white@ship8.com)
Status:	Signed
Transaction ID:	CBJCHBCAABAA2A61kvnwgHIJHHT75riBHQz6udWkSued

"12192025-SD3- 934007059-Adobe" History

-  Document created by Angele White (angele.white@ship8.com)
2025-12-19 - 6:53:15 PM GMT
-  Document emailed to James Burford (james.burford@ship8.com) for signature
2025-12-19 - 6:53:21 PM GMT
-  Document emailed to Ron Capranos (ron.capranos@ship8.com) for signature
2025-12-19 - 6:53:21 PM GMT
-  Email viewed by Ron Capranos (ron.capranos@ship8.com)
2025-12-19 - 7:11:13 PM GMT
-  Document e-signed by Ron Capranos (ron.capranos@ship8.com)
Signature Date: 2025-12-19 - 7:11:57 PM GMT - Time Source: server
-  Email viewed by James Burford (james.burford@ship8.com)
2025-12-20 - 2:09:57 AM GMT
-  Document e-signed by James Burford (james.burford@ship8.com)
Signature Date: 2025-12-20 - 2:11:34 AM GMT - Time Source: server
-  Agreement completed.
2025-12-20 - 2:11:34 AM GMT

 Outlook

Re: Completed: You're copied on "12192025-SD3- 934007059-Adobe"


From James Burford <james.burford@ship8.com>

Date Wed 1/28/2026 3:12 PM

To Christine Jenkins <christine.jenkins@ship8.com>; Angele White <Angele.White@ship8.com>

Cc Patrick Andreshack <patrick.andreshack@ship8.com>

I sent you an email on friday that it was completed. On this same thread.



SHIP8 INC.

James Burford
Regional Facilities Director
311 International Trade Pkwy
Port Wentworth, GA 31407

www.ship8.com

C:912.507.7881

From: Christine Jenkins <christine.jenkins@ship8.com>

Sent: Wednesday, January 28, 2026 7:18 AM

To: Angele White <Angele.White@ship8.com>; James Burford <james.burford@ship8.com>

Cc: Patrick Andreshack <patrick.andreshack@ship8.com>

Subject: Re: Completed: You're copied on "12192025-SD3- 934007059-Adobe"

Team

Has PO 25121442 been completed?



SHIP8 INC.

Christine Jenkins

Inv # 340116546
 Reference # 934007059
 Inv Date 1/5/2026
 Terms - Net 30
 Writer: REASSIGN IN TINNA

Road Service Invoice

Salesman:

BILL TO: 7253
 SHIP8 INC
 45875 NORTHPORT LOOP EAST
 Fremont, CA 94538
 510-490-9788

SHIP TO: 7255
 SHIP8 INC
 SD3
 311 INTERNATIONAL TRADE PKWY
 Savannah, GA 31407
 510-490-9788

Part #	Whse	Description	Bin	Qty	BO	Shipped	Each	Extended
141533	SAV	ENCODER BEARING 32 HALL R...	15C1	1	0	1	307.77	307.77
324100-018-10	SAV	HOSE - 10 FEET	New	1	0	1	214.73	214.73
363504-101	SAV	HYDRAULIC OIL AW32 GALLO...	RACK03FL	1	0	1	30.40	30.40
579	Brenton Quinn		12/16/2025	2			147.00	
619	John Silas		1/5/2026	1			147.00	
619	John Silas		1/5/2026	4.50			147.00	
1Z483122039195553	Inbound Frt	12/29CRO40592		1	0	1		50.00
Labor								661.50

Need to place a service call?

Please visit our website www.liftpower.com, click on service request, fill out the form and click submit. The next available service technician will be dispatched to you.

Invoices sent to collections will be subject to additional costs associated with collection of a debt over and above the original debt amount.

Sub Total **\$1,264.40**
 Tax **\$42.20**
 Total **\$1,306.60**

Inv # 340116546
 Reference # 934007059
 Inv Date 1/5/2026
 Terms - Net 30
 Writer: REASSIGN IN TINNA

Road Service Invoice

Salesman:

<p>BILL TO: 7253 SHIP8 INC 45875 NORTHPORT LOOP EAST Fremont, CA 94538 510-490-9788</p>	<p>SHIP TO: 7255 SHIP8 INC SD3 311 INTERNATIONAL TRADE PKWY Savannah, GA 31407 510-490-9788</p>
---	--

PO #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
25121442			CROWN	SP3520-30	1A589992	OP64	2017

Inspect & Quote. t is leaking hydraulic fluid and the height sensor need to be replaced. DO NOT REPAIR WITHOUT QUOTING FIRST. Cust rq.

This time has been added to quote 934007059

POC: Patrick Andreshak, 912.414.6118, patrick.andreshak@ship8.com

Quote to replace tank to pump hose and platform height encoder.

Diagnostic time from 340116546 has been added to this quote

Please email quote to sav.mait.management@ship8.com

WORK PERFORMED: Located lift. Inspected lift. Found hydraulic fluid on the floor. Customer mentioned platform height encoder needs replacing. Diagnosis was provided by prior tech. Cleaned off hose leaking. Ran lift. Hose continues to seep fluid from hose itself. Hose clamps are tight. Recommend replacing hose and new height encoder. Submitted quote.
 Brenton Quinn (2025-12-16)

Traveled to shop to get parts. Traveled to site. Found lift and had to carry tools and parts inside. Jacked up lift and blocked so that I could get drain pan under lift. Pulled one end of the hose off and put new hose on and pulled the end and got back on pump. Cleaned hydraulic fluid off lift where it was leaking. Filled with hydraulic fluid. Checked for leaks. Pulled ECR apart and removed old part and replaced with new one. Ran lift and it operated as it should checked again for leaks no current leaks at this time returned to service. Called Patrick to let him know that lift was repaired and good to go.
 John Silas (2026-01-05)