

**SHIP8, INC.**

ATTN: ACCOUNTS PAYABLE  
45875 NORTHPORT LOOP EAST  
FREMONT, CA 94538  
US  
AP.SHIP8@SHIP8.COM

PO No.

24030312

PO Date

03/19/2024

Page

1 OF 1

**ORDER FROM**

101144

PEARCE HEATING & AIR CONDITIONING, INC.  
PO BOX 1199  
WINTERS, CA 95694  
US

**SHIP TO**

WDC(4000),  
SHIP8, INC.  
ATTN: CHRISTINE JENKINS  
221 HANSON WAY  
WOODLAND, CA 95776  
US

**Buyer**

Purchasing Dept

**Terms**

30 days

**FOB**

FOB Origin

**Ship Via**

Best possible

Line No.	Vendor Item No.	Vendor Item Description	Qty Ordered	UOM	Unit Price	Extended Price
1	BLD003-HVAC Commercial Diagnostic	Provided a professional consultation to determine the customer's needs/concerns and/or solutions.	1.00	Each	125.00	

*5-19 JMC*

Total Extended Price =



Job #43444179

## Diagnostic Report ([B1] RTU\_15 sn: 344D (No heat))

### Customer Name

Ship 8 Inc.

### Technician

Paul A.



### Date

2023-10-27

### Reason For Call

No heat

### Data Plate



### Make

Manufacturer of the unit.

Trane

### Model/Product Number

Model/Product number of the unit.

YCD091D3LCBE

### Serial Number

Serial Number of the unit.

M12102344D

### Manufactured/Installed Date

Manufactured/Installed date of the unit.

1997

### Type of Unit

Type of Unit

Package Unit


### Type of Unit: Other

Type of unit if you chose other.

-

---

### Picture of Blower Motor




---

### Picture of Indoor Coil



---

### Picture of Filter



---

### Description of Findings

Inducer motor is receiving power but motor is completely seized up. Capacitor is in range and motor is hot to the touch. This motor is a complete assembly with the housing and wheel that would need to be replaced. This is a preliminary repair, there may be issues beyond just the motor. Due to the age of the system and the potential cost/availability of repairs, it's highly recommended to consider unit replacement. Diagnostic fee will be waived upon approval of an estimate.

---

### Repair Status:

Schedule Comfort Advisor.

---

### Customers Expectations

What are the customers expectations of next steps if any are needed

We will see if we can locate the inducer motor and assembly and provide an estimate for the

## Additional Pictures





Gmail

Search in mail



79

Compose



Mail

Inbox 338

### PO Request for Pearce - WDC - 43444179

Inbox x

Chat

Starred



**James Burford**

Christine, Please create a PO for the attached. The diagnostic findings are also attached to this file. James Burford Regional

Meet

Snoozed

Sent

Drafts 1



**Christine Jenkins**

PO 240303 (2 attached) Has this PO been completed? Christine Jenkins Purchasing Coordinator 550 Northport Parkway Port

Labels



**James Burford**

to me

Ok to pay



**SHIP8 INC.**

James Burford  
Regional Facilities Director  
311 International Trade Pkwy  
Port Wentworth, GA 31407

C:912.507.7881

Yes, it's done.

Yes, approved.

No, not yet.

Reply

Forward



Pearce Heating & Air Conditioning, Inc.  
 PO BOX 1199, Winters, CA 95694 United States  
 (530) 795-4300

**BILL TO**

Ship 8 Inc.  
 2222 East Beamer Street  
 Woodland, CA 95776 USA

<b>INVOICE</b> 43444179	<b>INVOICE DATE</b> Oct 27, 2023
----------------------------	-------------------------------------

**JOB ADDRESS**

Ship 8 Inc.  
 2222 East Beamer Street  
 Woodland, CA 95776 USA

**Completed Date:** 10/27/2023  
**Payment Term:** Due Upon Receipt  
**Due Date:** 10/27/2023

TASK	DESCRIPTION	QTY	PRICE	TOTAL
Commercial Diagnostic	Provided a professional consultation to determine the customer's needs/concerns and/or solutions.	1.00	\$125.00	\$125.00

TRANE YCD091D3LCBE S/N: M12102344D

<b>POTENTIAL SAVINGS</b>	\$0.00
<b>SUB-TOTAL</b>	\$125.00
<b>TAX</b>	\$0.00
<b>TOTAL DUE</b>	\$125.00
<b>BALANCE DUE</b>	\$125.00

Thank you for choosing Pearce Heating & Air Conditioning, Inc.

This invoice is agreed and acknowledged. Payment is due upon receipt. A service fee will be charged for any returned checks, and a financing charge of 1% per month shall be applied for overdue amounts.