

**SHIP8, INC.**

ATTN: ACCOUNTS PAYABLE  
45875 NORTHPORT LOOP EAST  
FREMONT, CA 94538

US

AP.SHIP8@SHIP8.COM

**ORDER FROM**

1089

LIFT POWER INC.

JACKSONVILLE, FL 32254

**Buyer**

Purchasing Dept

**Terms**

Net 30 Days

**FOB**

FOB Origin

**Ship Via**

Best possible

**SHIP TO**

SD3(3000),  
SHIP8, INC.  
ATTN: CHRISTINE JENKINS  
311 INTERNATIONAL TRADE PARKWAY  
PORT WENTWORTH, GA 31407  
US

**PO No.**

24070741

**PO Date**

07/02/2024

**Page**

1 OF 1

Line No.	Vendor Item No.	Vendor Item Description	Qty Ordered	UOM	Unit Price	Extended Price
1	EQU021	LABOR	1.00	Each		696.50

72-24

**Total Extended Price =**



# LIFTPOWER

Industrial Trucks • Materials Handling Equipment

6801 Suemac Place

Jacksonville, FL 32254

(904) 783-0250 | Fax (904) 781-1451

Quote # 934005444

Reference # 340098574

Quote Date 7/2/2024

Terms - Net 30

## Road Service Quote

Salesman: House: CSSR

Writer:

### BILL

TO: 7253  
SHIP8 INC  
45875 NORTHPORT LOOP EAST  
Fremont, CA 94538  
510-490-9788

### SHIP

TO: 7255  
SHIP8 INC  
SD3  
311 INTERNATIONAL TRADE PKWY  
Savannah, GA 31407  
510-490-9788

PO #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
			GENIE	GS3246	GS4613A-115282	SCISSOR LIFT	656

Quote to repair wiring issue in control box

Contact James B. james.burford@ship8.com

Part #	Whse	Description	Bin	Extended
Labor				696.50

# Quote

This Quotation is valid for 30 days.

This Quotation is subject to +/- 10% variation based on cost. (Freight is only an estimate).

Any Additional work found will be quoted for customer approval.

Sub Total	\$696.50
Tax	\$0.00
Total	\$696.50

> Favorites

> Folders

- Inbox 441
- Drafts 1
- Sent Items 5
- Deleted Items 408
- Junk Email 6
- Archive
- Notes
- Conversation History
- Create new folder
- Search Folders

Go to new Groups

✕ < >

**PO Request for Lift Power - SD3 - 934005444** ▾

JB

*PO # 2410 70741*

😊 ↩ Reply ↶ Reply all ↷ Forward 📧

To: Christine Jenkins; sav.maint.m Tue 7/2/2024 11:49 AM

This is completed.



**SHIP8 INC.**

James Burford  
 Regional Facilities Director  
 311 International Trade Pkwy  
 Port Wentworth, GA 31407

C:912.507.7881

...

↩ Reply   ↶ Reply all   ↷ Forward



**Industrial Trucks • Materials Handling Equipment**  
 801 Suemac Place  
 Jacksonville, FL 32254  
 (904) 783-0250 | Fax (904) 781-1451

Inv # 340098574  
 Reference # 934005444  
 Inv Date 7/5/2024  
 Terms - Net 30

## Road Service Invoice

Salesman: House CSSR

Writer:

**BILL TO:**  
 7253  
 SHIP8 INC  
 45875 NORTHPORT LOOP EAST  
 Fremont, CA 94538  
 510-490-9788

**SHIP TO:**  
 7255  
 SHIP8 INC  
 SD3  
 311 INTERNATIONAL TRADE PKWY  
 Savannah, GA 31407  
 510-490-9788

Q #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
1070741			GENIE	GS3246	GS4613A-115282	SCISSOR LIFT	656

Scissor lift with unk issues // Customer req Branden W  
 quote to repair wiring issue in control box.  
 contact James B james.burford@ship8.com

**WORK PERFORMED:** Unit reports low battery when fully charged and goes into limp mode on startup. Batteries test good, though not great voltage levels. Disassembled control handle to determine voltages received by controller. This is either a controller fault, or a wiring issue. Do not currently have a book on this truck.

Left red to white 25.5v (full bat), red to orange 24.9v, red to brown 25.5

Right: red to orange 22.8 (low bat), red white 0.6v, red brown 25.5

appears system voltage dropping when truck is turned on while battery voltage remains at operational levels.

Arcus Baumgartner (2024-06-27)

obtained truck service manual and wiring diagram which was necessary to further troubleshoot unit.

Arcus Baumgartner (2024-07-01)

Returned to site. Accessed lift. Continued to troubleshoot. Verified contactor good, fuses good, and chassis wiring harness good. Pinned-out main control cable to check for breaks or higher than normal resistance. All tested good. Disassembled control box again, and tested for continuity and connection issues. Found connection issues in controller B+/B- connection. Repaired connection by tightening individual pins in connector, and adjusting cable to relieve tension inside control box. Found that this resolved problem. Tested, moved unit back to shop and returned to service.

Arcus Baumgartner (2024-07-01)

# LIFTPOWER

Industrial Trucks • Materials Handling Equipment

801 Suemac Place  
Jacksonville, FL 32254  
(904) 783-0250 | Fax (904) 781-1451

Inv # 340098574  
Reference # 934005444  
Inv Date 7/5/2024  
Terms - Net 30

## Road Service Invoice

Salesman: House CSSR

Writer:

JLL  
O: 7253  
SHIP8 INC  
45875 NORTHPORT LOOP EAST  
Fremont, CA 94538  
510-490-9788

SHIP  
TO: 7255  
SHIP8 INC  
SD3  
311 INTERNATIONAL TRADE PKWY  
Savannah, GA 31407  
510-490-9788

Part #	Whse	Description	Bin	Extended
ibot				696.50

Need to place a service call?  
Please visit our website [www.liftpower.com](http://www.liftpower.com), click on service request, fill out the form and click submit. The next available service technician will be dispatched to you.

Invoices sent to collections will be subject to additional costs associated with collection of a debt over and above the original debt amount.

Sub Total	\$696.50
Tax	\$0.00
Total	\$696.50