

SHIP8, INC.

ATTN: ACCOUNTS PAYABLE
45875 NORTHPORT LOOP EAST
FREMONT, CA 94538

US

AP.SHIP8@SHIP8.COM

ORDER FROM

1069

LIFT POWER INC.

JACKSONVILLE, FL 32254

SHIP TO

SD3(3000),
SHIP8, INC.
ATTN: CHRISTINE JENKINS
311 INTERNATIONAL TRADE PARKWAY
PORT WENTWORTH, GA 31407
US

Buyer

Terms

FOB

Ship Via

Purchasing Dept

Net 30 Days

FOB Origin

Best possible

Line Itc.

Vendor Item No.

Vendor Item Description

Qty Ordered

UOM

Unit Price

Extended Price

1 EQU021

FLAT RATE LABOR

1.00

Each

551.25

JW 7-21

Total Extended Price =

LIFTPOWER

Industrial Trucks - Materials Handling Equipment
6801 Suemac Place
Jacksonville, FL 32254
(904) 783-0250 | Fax (904) 781-1451

Quote # 934006410
Reference # 340109783
Quote Date 6/6/2025
Terms - Net 30
Salesman: DAVID SPIRES Writer: TQ261497

Road Service Quote

BILL TO: 7253
SHIP8 INC
45875 NORTHPORT LOOP EAST
Fremont, CA 94538
510-490-9788

SHIP TO: 7255
SHIP8 INC
SD3
311 INTERNATIONAL TRADE PKWY
Savannah, GA 31407
510-490-9788

PO #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
			CROWN	SP3520-30	1A427705	R2409	8656

Per Leslie, send quote as diagnostics only from 340109783

Email quote to [HYPERLINK "mailto:sav.maint.management@ship8.com" sav.maint.management@ship8.com](mailto:sav.maint.management@ship8.com)

Part #	Whse	Description	Bin	Extended
Labor				551.25

Quote

This Quotation is valid for 30 days.
This Quotation is subject to +- 10% variation based on cost (Freight is only an estimate).
Any Additional work found will be quoted for customer approval.

Sub Total	\$551.25
Tax	\$0.00
Total	\$551.25






2025 07 10 SD3 Lift Power 934006410 R2409

Final Audit Report

2025-07-10

Created:	2025-07-10
By:	James Burford (james.burford@ship8.com)
Status:	Signed
Transaction ID:	CBJCHBCAABAAu3GUJdykMfytzW0MK9RU2iAZ-CTOXM


"2025 07 10 SD3 Lift Power 934006410 R2409" History

-  Document created by James Burford (james.burford@ship8.com)
2025-07-10 - 1:50:49 PM GMT
-  Document emailed to Ron Capranos (ron.capranos@ship8.com) for signature
2025-07-10 - 1:50:54 PM GMT
-  Email viewed by Ron Capranos (ron.capranos@ship8.com)
2025-07-10 - 1:53:01 PM GMT
-  Document e-signed by Ron Capranos (ron.capranos@ship8.com)
Signature Date: 2025-07-10 - 1:53:15 PM GMT - Time Source: server
-  Agreement completed.
2025-07-10 - 1:53:15 PM GMT

Re: Completed: You're copied on "2025 07 10 SD3 Lift Power 934006410 R2409"

From James Burford <james.burford@ship8.com>
Date Mon 7/21/2025 3:13 PM
To Christine Jenkins <christine.jenkins@ship8.com>

Yes, it was.



SHIP8 INC.

James Burford
Regional Facilities Director
311 International Trade Pkwy
Port Wentworth, GA 31407

C:912.507.7881

From: Christine Jenkins <christine.jenkins@ship8.com>
Sent: Monday, July 21, 2025 8:53 AM
To: James Burford <james.burford@ship8.com>
Subject: Re: Completed: You're copied on "2025 07 10 SD3 Lift Power 934006410 R2409"

Hi James

Was the labor completed for po25070687?



SHIP8 INC.

Christine Jenkins
Purchasing Coordinator

LIFTPOWER

Industrial Trucks • Materials Handling Equipment

6801 Suemac Place
Jacksonville, FL 32254
(904) 783-0250 | Fax (904) 781-1451

Inv # 340109783
Reference # 934006410
Inv Date 7/14/2025
Terms - Net 30
Writer: Wilfred N

Road Service Invoice

Salesman:

BILL TO: 7253 SHIP8 INC 45875 NORTHPORT LOOP EAST Fremont, CA 94538 510-490-9788	SHIP TO: 7255 SHIP8 INC SD3 311 INTERNATIONAL TRADE PKWY Savannah, GA 31407 510-490-9788
---	--

PO #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
25070687			CROWN	SP3520-30	1A427705	R2409	8656

Lift is bouncy. PM Follow Up rq Wilfred N

WORK PERFORMED: While at customer location maintenance drove me around the warehouse to look for the lift, once lift was located I can see where the platform looked bent. The maintenance guy operated lift up while I was watching the higher you go up the farther the platform leans. There is about a 2 in bend from the platform to the mast. The maintenance guy stated a operated hit something and it's been like that since that happen. Reached out to rental to see what needs to happen that if is also tagged out.
Dustin Triance (2025-05-23)

Drove to customer located lift it was in use, moved lift to work area felt it bouncing, checked wheels found drive tire and left load wheels to have damage, submitted quote. Returned lift to customer.
Drake Calhoun (2025-06-06)

Part #	Whse	Description	Bin	Extended
		Labor		551.25

Need to place a service call?

Please visit our website www.liftpower.com, click on service request, fill out the form and click submit. The next available service technician will be dispatched to you.

Invoices sent to collections will be subject to additional costs associated with collection of a debt over and above the original debt amount.

Sub Total	\$551.25
Tax	\$0.00
Total	\$551.25