

Jolly Roofing & Contracting Co., LLC.
 711 Chaney Cove
 Collierville, TN 38017
 901-854-5393



INVOICE

Zagam LLC
 45875 Northport Loop East
 Fremont, CA 94538

DATE 07/24/2025
 DUE DATE 08/23/2025
 INVOICE # 2332751
 Class 4/GGLA
 Sub Class AFLA

PROPERTY:
 JLA
 2101 Millers Ferry Road
 Wilmer, TX 75172

DESCRIPTION	AMOUNT
Travel: (Aaron Flack) 0.5hrs @ \$89.00/hr	\$44.50
Travel: (Technician #2) 0.5hrs @ \$89.00/hr	\$44.50
Labor: (Aaron Flack) 0.5hrs @ \$95.00/hr	\$47.50
Labor: (Technician #2) 0.5hrs @ \$95.00/hr	\$47.50
TPO Membrane 1 Ea. @ \$110.00	\$110.00
Equipment Fee 1 EA @ \$30.00	\$30.00
State Toll Fee 1 EA @ \$6.00	\$6.00

WORK PERFORMED
 Met with Miranda, located leak areas on roof. Found Warranty 1 open lap and Non-Warranty 1 burn hole. Repaired per industry standards.
 Description: Billing per fcs

SUBTOTAL \$330.00
 BALANCE DUE \$330.00

Please make all checks payable to:
Jolly Roofing and Contracting Co., LLC.
PO Box 55360
Little Rock, AR 72215
Please Include Invoice # on Checks


Net 30 Days

If you have any questions about this invoice, please contact
 Billing Support at billing@jollyroofing.com
Thank you for your business.



Property:
 JLA
 2101 Millers Ferry Road
 Wilmer, TX 75172

INVOICE # 2332751
 Class: 4/GGLA
 Zagam LLC
 45875 Northport Loop East
 Fremont, CA 94538



Distributed By: Jolly Roofing and Contracting Co, LLC.

Date dispatched: 07/09/2025


Time dispatched: 08:09 AM CST

JR

Acknowledged: 07/11/2025 02:06 PM

Signed: Aaron Flack

1 Problem:
 Burn/Scrim



The membrane has been burned, exposing the scrim causing premature failure.

1 Corrective Action:




Repaired per industry standards.



Property:
JLA
2101 Millers Ferry Road
Wilmer, TX 75172

INVOICE # 2332751
Class: 4/GGLA
Zagam LLC
45875 Northport Loop East
Fremont, CA 94538



Distributed By: Jolly Roofing and Contracting Co, LLC.

Date dispatched: 07/09/2025
Time dispatched: 08:09 AM CST

Handwritten signature

Acknowledged: 07/11/2025 02:06 PM
Signed: Aaron Flack

2 Problem:
Open Seams



Open seams in the roofing membrane.

2 Corrective Action:



Repaired per industry standards.



Signature Form

The signature below is to verify the information is true and correct.

JOB NAME: ILA

TECH 1: A Flack

ARRIVAL TIME: 11:00

DEPARTURE TIME: 1:30

TECH 2: Luke N.

ARRIVAL TIME: 11:00

DEPARTURE TIME: 1:30

SITE CONTACT: Miranda

DATE: 7-11-25

CONTACT SIGNATURE: Unavailable [Signature]