



Inspected Property:
 Date: 12/02/2025 Phone: 507-7881
 Name: Ship8
 Address: 550 Northport Pkwy
 City: PORT WENTWORTH State: GA Zip: 31407

Signatures/Owner Information

Property Owner:
 Name: Ship8 Phone:
 Address: 1680 TIDE COURT
 City: WOODLAND State: CA Zip: 95776

Monthly Inspection Report:
 Performed every month
 Date of Last Inspection: 11/05/2025
 Notes:

I state that the information on this form is correct at the time and place of my inspection and that all the equipment tested at this time was left in operational condition upon completion of that inspection except as noted.	Inspector - Printed: Jeffrey Hobart	Inspector - Signature: 	Date: 12/2/2025 Start Finish
	I state the building is occupied with the same occupancy classification and hazard of contents as last inspection. Also, the system has remained in service without modification and has been free of actuation of devices or alarms.	Owner Rep. - Printed:	Owner Rep. - Signature:

Inspection Questions	Y	N	N/a	Inspection Questions	System #							
					29&30	6&21	1&2	PM2	18	17	13	
Start Up Questions				All system type Questions								
1) Number of systems? Wet 34Dry Other:				3) Gauges in good condition, showing normal pressure, & calibrated / changed in the last 5 yrs?	Y	Y	Y	Y	Y	Y	Y	Y
2) System in service before testing?	<input checked="" type="checkbox"/>			4) Alarm devices appear to be damage free?	Y	Y	Y	Y	Y	Y	Y	Y

Table 1.1

Type of System	Wet	Wet	Wet	Wet	Wet	Wet	Wet	Wet	Wet	Wet	Wet
	29	30	26	25	21	22	PM2	18	17	robots/13	
Location / System #	29	30	26	25	21	22	PM2	18	17	robots/13	
Aux Drain Drained?	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Valve Type	Butterfly	Butterfly	Butterfly	Butterfly	Butterfly	Butterfly	Butterfly	Butterfly	Butterfly	Butterfly	
Size	6	6	6	6	6	6	4	6	6	6	
Secured	N	N	N	N	Y	Y	Y	Y	Y	Y	
Valve Inspection	Leakage	N	N	N	N	N	N	N	N	N	
	Appropriate Position (open/Closed)	Y	Y	Y	Y	Y	Y	Y	Y	Y	
	Accessible	Y	Y	Y	Y	Y	Y	Y	Y	Y	
	Signs	Y	Y	Y	Y	Y	Y	N	Y	Y	Y



825 Wheaton Street | Savannah, GA 31401 www.championfp.com
Office: 912-234-0111 Fax: 912-236-1303

Inspected Property:
 Date: 12/02/2025 Phone: 507-7881
 Name: Ship8
 Address: 550 Northport Pkwy
 City: PORT WENTWORTH State: GA Zip: 31407

Signatures/Owner Information

Property Owner:
 Name: Ship8 Phone:
 Address: 1680 TIDE COURT
 City: WOODLAND State: CA Zip: 95776

Monthly Inspection Report:
 Performed every month
 Date of Last Inspection: 11/05/2025
 Notes:

I state that the information on this form is correct at the time and place of my inspection and that all the equipment tested at this time was left in operational condition upon completion of that inspection except as noted.	Inspector - Printed: Jeffrey Hobart	Inspector - Signature: 	Date: 12/2/2025 Start Finish
	I state the building is occupied with the same occupancy classification and hazard of contents as last inspection. Also, the system has remained in service without modification and has been free of actuation of devices or alarms.	Owner Rep. - Printed:	Owner Rep. - Signature:

Inspection Questions	Y	N	N/a	Inspection Questions	System #							
					9	4&11	5&6	2&1	4	3	7	
Start Up Questions				All system type Questions								
1) Number of systems? Wet 34Dry Other:				3) Gauges in good condition, showing normal pressure, & calibrated / changed in the last 5 yrs?	Y	Y	Y	Y	Y	Y	Y	Y
2) System in service before testing?	<input checked="" type="checkbox"/>			4) Alarm devices appear to be damage free?	Y	Y	Y	Y	Y	Y	Y	Y

Table 1.1

Type of System	Wet	Wet	Wet	Wet	Wet	Wet	Wet	Wet	Wet	Wet	Wet
Location / System #	robots/9	robots/14	robots/10	robots/5	robots/6	robots/2	robots/1	4	3	7	
Aux Drain Drained?	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Valve Type	Butterfly	Butterfly	Butterfly	Butterfly	Butterfly	Butterfly	Butterfly	Butterfly	Butterfly	Butterfly	Butterfly
Size	6	6	6	6	6	6	6	6	6	6	6
Secured	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
Valve Inspection	Leakage	N	N	N	N	N	N	N	N	N	N
	Appropriate Position (open/Closed)	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
	Accessible	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
	Signs	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y



Inspected Property:
 Date: 12/02/2025 Phone: 507-7881
 Name: Ship8
 Address: 550 Northport Pkwy
 City: PORT WENTWORTH State: GA Zip: 31407

Signatures/Owner Information

Property Owner:
 Name: Ship8 Phone:
 Address: 1680 TIDE COURT
 City: WOODLAND State: CA Zip: 95776

Monthly Inspection Report:
 Performed every month
 Date of Last Inspection: 11/05/2025
 Notes:

I state that the information on this form is correct at the time and place of my inspection and that all the equipment tested at this time was left in operational condition upon completion of that inspection except as noted.	Inspector - Printed: Jeffrey Hobart	Inspector - Signature: 	Date: 12/2/2025 Start Finish
	I state the building is occupied with the same occupancy classification and hazard of contents as last inspection. Also, the system has remained in service without modification and has been free of actuation of devices or alarms.	Owner Rep. - Printed:	Owner Rep. - Signature:

Inspection Questions	Y	N	N/a	Inspection Questions	System #							
					8	1&11	2&10	0&19	33	23	24	
Start Up Questions				All system type Questions								
1) Number of systems? Wet 34Dry Other:				3) Gauges in good condition, showing normal pressure, & calibrated / changed in the last 5 yrs?	Y	Y	Y	Y	Y	Y	Y	Y
2) System in service before testing?	<input checked="" type="checkbox"/>			4) Alarm devices appear to be damage free?	Y	Y	Y	Y	Y	Y	Y	Y

Table 1.1

Type of System	Wet	Wet	Wet	Wet	Wet	Wet	Wet	Wet	Wet	Wet	Wet
	8	11	15	12	16	20	19	33	23	24	
Location / System #	8	11	15	12	16	20	19	33	23	24	
Aux Drain Drained?	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Valve Type	Butterfly	Butterfly	Butterfly	Butterfly	Butterfly	Butterfly	Butterfly	Butterfly	Butterfly	Butterfly	
Size	6	6	6	6	6	6	6	4	6	6	
Secured	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	
Valve Inspection	Leakage	N	N	N	N	N	N	N	N	N	
	Appropriate Position (open/Closed)	Y	Y	Y	Y	Y	Y	Y	Y	Y	
	Accessible	Y	Y	Y	Y	Y	Y	Y	Y	Y	
	Signs	Y	Y	Y	Y	Y	N	Y	Y	Y	



Inspected Property:
 Date: 12/02/2025 Phone: 507-7881
 Name: Ship8
 Address: 550 Northport Pkwy
 City: PORT WENTWORTH State: GA Zip: 31407

Signatures/Owner Information

Property Owner:
 Name: Ship8 Phone:
 Address: 1680 TIDE COURT
 City: WOODLAND State: CA Zip: 95776

Monthly Inspection Report:
 Performed every month
 Date of Last Inspection: 11/05/2025
 Notes:

I state that the information on this form is correct at the time and place of my inspection and that all the equipment tested at this time was left in operational condition upon completion of that inspection except as noted.	Inspector - Printed: Jeffrey Hobart	Inspector - Signature: 	Date: 12/2/2025 Start Finish
	I state the building is occupied with the same occupancy classification and hazard of contents as last inspection. Also, the system has remained in service without modification and has been free of actuation of devices or alarms.	Owner Rep. - Printed:	Owner Rep. - Signature:

Inspection Questions	Y	N	N/a	Inspection Questions	System #							
					28	27	31	32	pump	pump	pump	
Start Up Questions				All system type Questions								
1) Number of systems? Wet 34Dry Other:				3) Gauges in good condition, showing normal pressure, & calibrated / changed in the last 5 yrs?	Y	Y	Y	Y	-	-	-	
2) System in service before testing?	<input checked="" type="checkbox"/>			4) Alarm devices appear to be damage free?	Y	Y	Y	Y	Y	Y	Y	

Table 1.1

Type of System	Wet	Wet	Wet	Wet	Wet	Wet	Wet	Wet	Wet	Wet	Wet
	28	27	31	32	pump suction	pump discharge	JP suction	JP discharge	Bypass #1	Bypass #2	
Aux Drain Drained?	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Valve Type	Butterfly	Butterfly	Butterfly	Butterfly	OS&Y	Butterfly	Butterball	Butterball	Butterfly	Butterfly	
Size	6	6	6	6	10	10	1	1	10	10	
Secured	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	
Valve Inspection	Leakage	N	N	N	N	N	N	N	N	N	
	Appropriate Position (open/Closed)	Y	Y	Y	Y	Y	Y	Y	Y	Y	
	Accessible	Y	Y	Y	Y	Y	Y	Y	Y	Y	
	Signs	Y	Y	Y	Y	N	N	N	N	N	N



825 Wheaton Street | Savannah, GA 31401 www.championfp.com
Office: 912-234-0111 Fax: 912-236-1303

Inspected Property:
 Date: 12/02/2025 Phone: 507-7881
 Name: Ship8
 Address: 550 Northport Pkwy
 City: PORT WENTWORTH State: GA Zip: 31407

Signatures/Owner Information

Property Owner:
 Name: SHIP8 Phone:
 Address: 1680 TIDE COURT
 City: WOODLAND State: CA Zip: 95776

Monthly Inspection Report:
 Performed every month
 Date of Last Inspection: 11/05/2025
 Notes:

I state that the information on this form is correct at the time and place of my inspection and that all the equipment tested at this time was left in operational condition upon completion of that inspection except as noted.	Inspector - Printed: Jeffrey Hobart	Inspector - Signature: 	Date: 12/2/2025 Start Finish
	I state the building is occupied with the same occupancy classification and hazard of contents as last inspection. Also, the system has remained in service without modification and has been free of actuation of devices or alarms.	Owner Rep. - Printed:	Owner Rep. - Signature:

Inspection Questions	Y	N	N/a	Inspection Questions	System #							
Start Up Questions				All system type Questions								
1) Number of systems? Wet 34Dry0 Other:				3) Gauges in good condition, showing normal pressure, & calibrated / changed in the last 5 yrs?	-	-	-	-	-	-	-	-
2) System in service before testing?	✓			4) Alarm devices appear to be damage free?	Y	Y	Y	Y	Y	Y	Y	Y

Table 1.1

Type of System	Dry	Wet	Wet	Wet	Wet	Wet	Wet	Wet	Wet	Wet	-
	Location / System #	Test header	BF suction	BF discharge	BF bypass	BF bypass #	yard	yard	yard	yard	yard
Aux Drain Drained?	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Valve Type	Butterfly	OS&Y	OS&Y	ball	ball	PIV	PIV	PIV	PIV	PIV	
Size	10	10	10	3/4	3/4						
Secured	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	-
Valve Inspection	Leakage	N	N	N	N	N	N	N	N	N	-
	Appropriate Position (open/Closed)	Y	Y	Y	Y	Y	Y	Y	Y	Y	-
	Accessible	Y	Y	Y	Y	Y	Y	Y	Y	Y	-
	Signs	N	N	N	N	N	Y	Y	Y	Y	-

