

SHIP8, INC.

ATTN: ACCOUNTS PAYABLE
 45875 NORTHPORT LOOP EAST
 FREMONT, CA 94538

US

AP.SHIP8@SHIP8.COM

ORDER FROM

1069

LIFT POWER INC.

JACKSONVILLE, FL 32254

SHIP TO

SD3(3000),
 SHIP8, INC.
 ATTN: CHRISTINE JENKINS
 311 INTERNATIONAL TRADE PARKWAY
 PORT WENTWORTH, GA 31407
 US

PO No.

26040519

Page

04/30/2026

1 OF 1

Buyer

Purchasing Dept

Terms

Net 30 Days

FOB

FOB Origin

Ship Via

Best possible

Line No.	Vendor Item No.	Vendor Item Description	Qty Ordered	UOM	Unit Price	Extended Price
1	149335	Reach Secondary CYL	1.00	Each	198.05	198.05
2	363504-101	HYDRAULIC OIL AW32 GALLON JUG	1.00	Each	30.40	30.40
3	363147-001	Brake Cleaner	1.00	Each	7.76	7.76
4	MSC023-SHIPPING/FREIGHT	INBOUND FREIGHT QUOTE	1.00	Each	35.00	35.00
5	EQU021	FLAT RATE LABOR	1.00	Each	1,051.05	1,051.05

5-14 *gm*

[Handwritten mark]

Total Extended Price =

LIFTPOWER

Industrial Trucks • Materials Handling Equipment

6801 Suemac Place

Jacksonville, FL 32254

(904) 783-0250 | Fax (904) 781-1451

Quote # 934007521

Reference # 340120372

Quote Date 4/23/2026

Terms - Net 30

Road Service Quote

Salesman: House CSSR

Writer: TQ384581

BILL TO:

7253
SHIP8 INC
45875 NORTHPORT LOOP EAST
Fremont, CA 94538
510-490-9788

SHIP TO:

7255
SHIP8 INC
SD3
311 INTERNATIONAL TRADE PKWY
Savannah, GA 31407
510-490-9788

PO #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
			CROWN	RR5725-45	1A590150	1A590150	4883.7001953125

Quote to replace seal kit in secondary lift cylinder

Diagnostic time from 340120372 has been added to this quote.

Please email quote to sav.maint.management@ship8.com

Part #	Whse	Description	Bin	Qty	Each	Extended
149335	SAV	REACH SECONDARY CYL SEAL ...	18E2	1	198.05	198.05
363504-101	SAV	HYDRAULIC OIL AW32 GALLO...	RACK03FL	1	30.40	30.40
363147-001	SAV	BRAKE CLEANER HIGH VOC CAN07A		1	7.76	7.76
Estimated Inbound Freight				1		35.00
Flat Rate Labor						1,051.05

Quote

This Quotation is valid for 30 days.

This Quotation is subject to +- 10% variation based on cost (Freight is only an estimate).

Any Additional work found will be quoted for customer approval.

Sub Total	\$1,322.26
Tax	\$18.98
Total	\$1,341.24









04302026-SD3-934007521-LiftPower

Final Audit Report

2026-04-30

Created:	2026-04-30
By:	Angele White (angele.white@ship8.com)
Status:	Signed
Transaction ID:	CBJCHBCAABAA5WmjHS9ZG6ouqDnTS_W9qmLOW654AkCb

"04302026-SD3-934007521-LiftPower" History

-  Document created by Angele White (angele.white@ship8.com)
2026-04-30 - 2:41:31 PM GMT
-  Document emailed to James Burford (james.burford@ship8.com) for signature
2026-04-30 - 2:41:37 PM GMT
-  Document emailed to Ron Capranos (ron.capranos@ship8.com) for signature
2026-04-30 - 2:41:37 PM GMT
-  Email viewed by Ron Capranos (ron.capranos@ship8.com)
2026-04-30 - 2:41:54 PM GMT
-  Document e-signed by Ron Capranos (ron.capranos@ship8.com)
Signature Date: 2026-04-30 - 2:42:13 PM GMT - Time Source: server
-  Email viewed by James Burford (james.burford@ship8.com)
2026-04-30 - 2:59:25 PM GMT
-  Document e-signed by James Burford (james.burford@ship8.com)
Signature Date: 2026-04-30 - 2:59:35 PM GMT - Time Source: server
-  Agreement completed.
2026-04-30 - 2:59:35 PM GMT



1500 Jimmy Deloach Pkwy, Suite 100
 Pooler, GA 31415
 912-447-9500
 liftpower.com

Customer
 SHIP8 INC
 311 INTERNATIONAL TRADE PKWY
 Savannah, GA 31407
 510-490-9788
 PO Number: 26040519

Work Order
 340120372

Date Completed
 2026-05-14

Work Order Type
 Service

Person
 William Long

Equipment
 S/N: 1A590150
 Make: CROWN
 Model: RR5725-45
 Meter: 4975.5
 Unit No.: 1A590150 / Internal No.: 1A590150

Labels
 Customer

Description
 Inspect & quote: Leak on the top of the mass of RT 33. Tech to confirm SN onsite. Customer req via email
 MUST QUOTE ALL REPAIRS

This time has been added to quote 934007521

Contact: Patrick Adreshak 912-414-6118

Work Performed

Arrived at customer location and located truck, inspected the truck and found the right side secondary cylinder is leaking from the seal in the cap. Quoting

By. William Long, Date: 2026-04-23

Arrived at customer location and located truck, lifted the mast into the air and blocked. Removed the bolt from the top of the ram and opened the bleeder, pushed the ram down and removed the cap from the top of the cylinder and replaced with new cap and seals. Put the truck back together and tested it with no leaks and no issues.

By. William Long, Date: 2026-05-14

Parts					
Date	Person	Part	Description	Location	Quantity
2026-04-30	LIFT POWER AGENT	363504-101	HYDRAULIC OIL AW32 GALLON JUG	SAV	1.00
2026-04-30	LIFT POWER AGENT	149335	REACH SECONDARY CYL SEAL KIT	SAV	1.00
2026-04-30	LIFT POWER AGENT	363147-001	BRAKE CLEANER HIGH VOC CA N	SAV	1.00

Travel & Labor			
Date	Person	Type	Quantity
2026-05-14	William Long	LABOR	3.50
2026-04-23	William Long	LABOR	1.50
2026-05-14	William Long	TRAVEL	1.00
2026-04-23	William Long	TRAVEL	1.00
TOTAL LABOR			5.00



1500 Jimmy Deloach Pkwy, Suite 100
Pooler, GA 31415
912-447-9500
liftpower.com

Customer
SHIP8 INC
311 INTERNATIONAL TRADE PKWY
Savannah, GA 31407
510-490-9788
PO Number: 26040519

Work Order
340120372

Work Order Type
Service

Date Completed
2026-05-14

Person
William Long

Equipment
S/N: 1A590150
Make: CROWN
Model: RR5725-45
Meter: 4975.5
Unit No.: 1A590150 / Internal No.: 1A590150

TOTAL TRAVEL

2.00

Misc. Charges

Item	Quantity
Estimated Inbound Freight	1.00

Signed By: William Long

Cancellation of Service: In the event that the customer cancels any repair work or denies any repairs that were quoted, the unit shall be reassembled to a condition reasonably similar as when first inspected unless customer waives reassembly or the reassembled unit would be unsafe. Customer will be responsible for charges incurred during teardown, the cost of parts and labor to replace items destroyed in teardown and the cost to reassemble.

Limited Warranty: All materials, parts and equipment are warranted by the manufacturer or suppliers written warranty only. All labor performed by the above named company is warranted for a period of 90 Days unless otherwise noted in writing. the above named company makes no other warranty, express or implied and its agents or technicians are not authorized to make any such warranties on behalf of the above named company. Terms: NET 30 Days

William Long


Re: Completed: You're copied on "04302026-SD3-934007521-LiftPower"

From Patrick Andreshack <patrick.andreshack@ship8.com>

Date Mon 5/18/2026 8:26 AM

To Christine Jenkins <christine.jenkins@ship8.com>; Angele White <Angele.White@ship8.com>; James Burford <james.burford@ship8.com>

completed



SHIP8 INC.

Patrick Andreshak
Maintenance Manager
550 Northport Parkway
Port Wentworth, GA 31407

C:912.414.6118

From: Christine Jenkins <christine.jenkins@ship8.com>

Sent: Friday, May 15, 2026 5:57 AM

To: Angele White <Angele.White@ship8.com>; James Burford <james.burford@ship8.com>

Cc: Patrick Andreshack <patrick.andreshack@ship8.com>

Subject: Re: Completed: You're copied on "04302026-SD3-934007521-LiftPower"

Team

Has PO 26040519 been completed?



SHIP8 INC.

Christine Jenkins
Purchasing Coordinator
550 Northport Parkway

LIFTPOWER

Industrial Trucks • Materials Handling Equipment

6801 Suemac Place
 Jacksonville, FL 32254
 (904) 783-0250 | Fax (904) 781-1451

Inv # 340120372
 Reference # 934007521
 Inv Date 5/14/2026
 Terms - Net 30
 Writer: REASSIGN

Road Service Invoice

Salesman: House CSSR

BILL TO: 7253
 SHIP8 INC
 45875 NORTHPORT LOOP EAST
 Fremont, CA 94538
 510-490-9788

SHIP TO: 7255
 SHIP8 INC
 SD3
 311 INTERNATIONAL TRADE PKWY
 Savannah, GA 31407
 510-490-9788

PO #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
26040519			CROWN	RR5725-45	1A590150	1A590150	4975.5

Inspect & quote: Leak on the top of the mass of RT 33. Tech to confirm SN onsite. Customer req via email
 MUST QUOTE ALL REPAIRS

This time has been added to quote: 934007521

Contact: Patrick Adreshak 912-414-6118

WORK PERFORMED: Arrived at customer location and located truck, inspected the truck and found the right side secondary cylinder is leaking from the seal in the cap. Quoting William Long (2026-04-23)

Arrived at customer location and located truck, lifted the mast into the air and blocked. Removed the bolt from the top of the ram and opened the bleeder, pushed the ram down and removed the cap from the top of the cylinder and replaced with new cap and seals. Put the truck back together and tested it with no leaks and no issues.
 William Long (2026-05-14)

Part #	Whse	Description	Bin	Qty	BO	Shipped	Each	Extended
149335	SAV	REACH SECONDARY CYL SEAL ...	18E2	1	0	1	198.05	198.05
363147-001	SAV	BRAKE CLEANER HIGH VOC CAN07A		1	0	1	7.76	7.76
363504-101	SAV	HYDRAULIC OIL AW32 GALLO... RACK03FL		1	0	1	30.40	30.40
Estimated Inbound Freight				1	0	1		35.00
Flat Rate Labor								1,051.05

LIFTPOWER

Industrial Trucks • Materials Handling Equipment

6801 Suemac Place

Jacksonville, FL 32254

(904) 783-0250 | Fax (904) 781-1451

Inv # 340120372

Reference # 934007521

Inv Date 5/14/2026

Terms - Net 30

Writer: REASSIGN

Road Service Invoice

Salesman: House CSSR

BILL

TO: 7253
SHIP8 INC
45875 NORTHPORT LOOP EAST
Fremont, CA 94538
510-490-9788

SHIP

TO: 7255
SHIP8 INC
SD3
311 INTERNATIONAL TRADE PKWY
Savannah, GA 31407
510-490-9788

Need to place a service call?

Please visit our website www.liftpower.com, click on service request, fill out the form and click submit. The

next available service technician will be dispatched to you.

Sub Total	\$1,322.26
Tax	\$18.98
Total	\$1,341.24