

**SHIP8, INC.**

ATTN: ACCOUNTS PAYABLE  
 45875 NORTHPORT LOOP EAST  
 FREMONT, CA 94538  
 US

AP.SHIP8@SHIP8.COM

ORDER FROM

1069

LIFT POWER INC.

JACKSONVILLE, FL 32254

SHIP TO

SD3(3000),  
 SHIP8, INC.  
 ATTN: CHRISTINE JENKINS  
 311 INTERNATIONAL TRADE PARKWAY  
 PORT WENTWORTH, GA 31407  
 US

Buyer

Purchasing Dept

Terms

Net 30 Days

FOB

FOB Origin

Ship Via

Best possible

Line No.	Vendor Item No.	Vendor Item Description	Qty Ordered	UOM	Unit Price	Extended Price
1	105000	Cover Pedal	1.00	Each	22.36	
2	130724-001	Cover Light Assembly	1.00	Each	148.07	
3	MSC023-	INBOUND FREIGHT QUOTE	1.00	Each	35.00	
4	EQU021	FLAT RATE LABOR	1.00	Each	242.55	

*Handwritten:* Jm. 5-28

Total Extended Price =



# LIFTPOWER

Industrial Trucks • Materials Handling Equipment

6801 Suemac Place

Jacksonville, FL 32254

(904) 783-0250 | Fax (904) 781-1451

Quote # 934007596

Reference # 347069512

Quote Date 5/13/2026

Terms - Net 30

## Road Service Quote

Salesman: House CSSR

Writer: TQ393924

### BILL TO:

7253  
SHIP8 INC  
45875 NORTHPORT LOOP EAST  
Fremont, CA 94538  
510-490-9788

### SHIP TO:

7255  
SHIP8 INC  
SD3  
311 INTERNATIONAL TRADE PKWY  
Savannah, GA 31407  
510-490-9788

PO #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
			CROWN	SP3220-30	1A266302	OP02	2636

Quote to replace missing brake padding and damaged strobe light cover.

These are recommended repairs from a recent PM Service.

Email quote to [sav.mait.management@ship8.com](mailto:sav.mait.management@ship8.com).

Part #	Whse	Description	Bin	Qty	Each	Extended
105000	SAV	COVER PEDAL	New	1	NA	22.36
130724-001	SAV	COVER LIGHT ASSEMBLY BLACK 22M2		1	NA	148.07
ESTIMATED INBOUND FREIGHT				1		35.00
Labor						242.55

# Quote

This Quotation is valid for 30 days.

This Quotation is subject to +/- 10% variation based on cost (Freight is only an estimate).

Any Additional work found will be quoted for customer approval.

Sub Total	\$447.98
Tax	\$14.38
Total	\$462.36






# 05152026-SD3-934007596-LiftPower

Final Audit Report

2026-05-15

Created:	2026-05-15
By:	Angele White (angele.white@ship8.com)
Status:	Signed
Transaction ID:	CBJCHBCAABAAaWEyodgXhTpZNFepYqRlMFLt6d7D2Td

## "05152026-SD3-934007596-LiftPower" History

-  Document created by Angele White (angele.white@ship8.com)  
2026-05-15 - 3:22:01 PM GMT
-  Document emailed to James Burford (james.burford@ship8.com) for signature  
2026-05-15 - 3:22:06 PM GMT
-  Email viewed by James Burford (james.burford@ship8.com)  
2026-05-15 - 5:41:44 PM GMT
-  Document e-signed by James Burford (james.burford@ship8.com)  
Signature Date: 2026-05-15 - 5:42:09 PM GMT - Time Source: server - Signature Appearance Selected: MOBILE\_IMAGE
-  Agreement completed.  
2026-05-15 - 5:42:09 PM GMT



1500 Jimmy Deloach Pkwy, Suite 100  
 Pooler, GA 31415  
 912-447-9500  
 liftpower.com

**Work Order**  
 340121116

**Date Completed**  
 2026-05-28

**Work Order Type**  
 Service

**Person**  
 Phillip Herzer

**Reference**  
 TQ393924

**Customer**  
 SHIP8 INC  
 311 INTERNATIONAL TRADE PKWY  
 Savannah, GA 31407  
 510-490-9788  
 PO Number: 26050586

**Equipment**  
 S/N: 1A266302  
 Make: CROWN  
 Model: SP3220-30  
 Meter: 2638.0  
 Unit No.: OP02 / Internal No.: 163059

**Labels**  
 Customer

**Description**  
 Quote to replace missing brake padding and damaged strobe light cover.

These are recommended repairs from a recent PM Service

Email quote to sav.mait.management@ship8.com.

**Work Performed**

Traveled to shop to pick up repair parts. Returned to customers location. Located lift. Removed/replaced strobe light cover. Installed cover/pad on brake pedal. Returned lift to service. Repair complete

By: Phillip Herzer, Date: 2026-05-28

Parts					
Date	Person	Part	Description	Location	Quantity
2026-05-18	LIFT POWER AGENT	130724-001	COVER LIGHT ASSEMBLY BLAC K	SAV	1.00
2026-05-18	LIFT POWER AGENT	105000	COVER PEDAL	SAV	1.00
Travel & Labor					
Date	Person	Type			Quantity
2026-05-28	Phillip Herzer	LABOR			1.93
2026-05-28	Phillip Herzer	TRAVEL			0.66
		<b>TOTAL LABOR</b>			<b>1.93</b>
		<b>TOTAL TRAVEL</b>			<b>0.66</b>
Misc. Charges					
Item					Quantity
INBOUND FREIGHT / 1Z4831220395086208 CR41569					1.00



1500 Jimmy Deloach Pkwy, Suite 100  
Pooler, GA 31415  
912-447-9500  
liftpower.com

**Customer**

SHIP8 INC  
311 INTERNATIONAL TRADE PKWY  
Savannah, GA 31407  
510-490-9788  
PO Number: 26050586

**Work Order**  
340121116

**Work Order Type**  
Service

**Reference**  
TQ393924

**Equipment**

S/N: 1A266302  
Make: CROWN  
Model: SP3220-30  
Meter: 2638.0  
Unit No.: OP02 / Internal No.: 163059

**Date Completed**  
2026-05-28

**Person**  
Phillip Herzer

**Customer Name: Patrick Andreshak**

Cancellation of Service: In the event that the customer cancels any repair work or denies any repairs that were quoted, the unit shall be reassembled to a condition reasonably similar as when first inspected unless customer waives reassembly or the reassembled unit would be unsafe. Customer will be responsible for charges incurred during teardown, the cost of parts and labor to replace items destroyed in teardown and the cost to reassemble.

Limited Warranty: All materials, parts and equipment are warranted by the manufacturer or suppliers written warranty only. All labor performed by the above named company is warranted for a period of 90 Days unless otherwise noted in writing. the above named company makes no other warranty, express or implied and its agents or technicians are not authorized to make any such warranties on behalf of the above named company. Terms: NET 30 Days

# LIFTPOWER

Industrial Trucks • Material Handling Equipment

6801 Suemac Place  
 Jacksonville, FL 32254  
 (904) 783-0250 | Fax (904) 781-1451

Inv # 340121116  
 Reference # 934007596  
 Inv Date 5/28/2026  
 Terms - Net 30  
 Writer: TQ393924

## Road Service Invoice

Salesman: DAVID SPIRES

**BILL**

TO: 7253  
 SHIP8 INC  
 45875 NORTHPORT LOOP EAST  
 Fremont, CA 94538  
 510-490-9788

**SHIP**

TO: 7255  
 SHIP8 INC  
 SD3  
 311 INTERNATIONAL TRADE PKWY  
 Savannah, GA 31407  
 510-490-9788

PO #	Ship.Via	FOB	Make	Model	Serial #	Unit #	Meter
26050586			CROWN	SP3220-30	1A266302	OP02	2638

Quote to replace missing brake padding and damaged strobe light cover.

These are recommended repairs from a recent PM Service

Email quote to [sav.mait.management@ship8.com](mailto:sav.mait.management@ship8.com).

WORK PERFORMED: Traveled to shop to pick up repair parts. Returned to customers location. Located lift. Removed/replaced strobe light cover. Installed cover/pad on brake pedal. Returned lift to service. Repair complete  
 Phillip Herzer (2026-05-28)

Part #	Whse	Description	Bin	Qty	BO	Shipped	Each	Extended
105000	SAV	COVER PEDAL	New	1	0	1	22.36	22.36
130724-001	SAV	COVER LIGHT ASSEMBLY BLACK 22M2		1	0	1	148.07	148.07
INBOUND FREIGHT / 1Z4831220395086208 CR41569				1	0	1		35.00
Labor								242.55

Need to place a service call?

Please visit our website [www.liftpower.com](http://www.liftpower.com), click on service request, fill out the form and click submit. The next available service technician will be dispatched to you.

Invoices sent to collections will be subject to additional costs associated with collection of a debt over and above the original debt amount.

Sub Total	\$447.98
Tax	\$14.38
Total	\$462.36