

SHIP8, INC.

ATTN: ACCOUNTS PAYABLE
45875 NORTHPORT LOOP EAST
FREMONT, CA 94538
US
AP.SHIP8@SHIP8.COM

PO No. 26060655
PO Date 06/08/2026
Page 1 OF 1

ORDER FROM

1069

LIFT POWER INC.

JACKSONVILLE, FL 32254

SHIP TO

SD2(2000),
SHIP8, INC.
ATTN: CHRISTINE JENKINS
550 NORTHPORT PARKWAY
PORT WENTWORTH, GA 31407
US

Buyer

Purchasing Dept

Terms

Net 30 Days

FOB

FOB Origin

Ship Via

Best possible

Vendor Item No. Vendor Item Description

1 EQU021

FLAT RATE LABOR

Qty Ordered

1.00

UOM

Each

Unit Price

404.25

Extended Price

End.

Total Extended Price =

LIFTPOWER

Industrial Trucks • Materials Handling Equipment

6801 Suemac Place
Jacksonville, FL 32254
(904) 783-0250 | Fax (904) 781-1451

Quote # 934007584
Reference # 340120869
Quote Date 5/12/2026
Terms - Net 30
Writer: TQ392972

Road Service Quote

Salesman: House CSSR

BILL TO: 7253 SHIP8 INC 45875 NORTHPORT LOOP EAST Fremont, CA 94538 510-490-9788	SHIP TO: 7255 SHIP8 INC SD3 311 INTERNATIONAL TRADE PKWY Savannah, GA 31407 510-490-9788
---	--

PO #	Ship Via	FOB	Make CROWN	Model C51000-50	Serial # 10222914	Unit # 10222914	Meter 3408.1999511719
-------------	-----------------	------------	----------------------	---------------------------	-----------------------------	---------------------------	---------------------------------

Quote to adjust brake handle.

Diagnostic time from 340120869 has been added to this quote

Email quote to sav.mait.management@ship8.com.

<i>Part #</i>	<i>Whse</i>	<i>Description</i>	<i>Bin</i>	<i>Extended</i>
Labor				404.25

Quote

This Quotation is valid for 30 days.

This Quotation is subject to +- 10% variation based on cost (Freight is only an estimate).

Any Additional work found will be quoted for customer approval.

Sub Total	\$404.25
Tax	\$0.00
Total	\$404.25

06092026-SD2- 934007584-LiftPower

Final Audit Report

2026-06-09

Created:	2026-06-09
By:	Angele White (angele.white@ship8.com)
Status:	Signed
Transaction ID:	CBJCHBCAABAAmgoaO06iwuhYyVgnmzUthGYKpz1TDbOb

"06092026-SD2- 934007584-LiftPower" History

-  Document created by Angele White (angele.white@ship8.com)
2026-06-09 - 12:06:38 PM GMT
-  Document emailed to James Burford (james.burford@ship8.com) for signature
2026-06-09 - 12:06:43 PM GMT
-  Email viewed by James Burford (james.burford@ship8.com)
2026-06-09 - 1:24:44 PM GMT
-  Document e-signed by James Burford (james.burford@ship8.com)
Signature Date: 2026-06-09 - 1:25:12 PM GMT - Time Source: server - Signature Appearance Selected: MOBILE_IMAGE
-  Agreement completed.
2026-06-09 - 1:25:12 PM GMT



1500 Jimmy Deloach Pkwy, Suite 100
 Pooler, GA 31415
 912-447-9500
 liftpower.com

Customer
 SHIP8 INC
 311 INTERNATIONAL TRADE PKWY
 Savannah, GA 31407
 510-490-9788
 PO Number: 26060655

Labels
 Customer

Description
 Inspect & quote. DO NOT COMPLETE ANY REPAIRS WITHOUT QUOTING FIRST. Parking brake needs adjustments, difficulty in moving. Brakes making a squeezing noise when driving fwd. PM Follow Up Jimmie Al.

This time has been added to quote 934007584

Work Performed

Inspected the truck and found that the service brake handle was adjusted up to much causing it to bind, need to adjust brake handle so it pulls back with ease and releases the same. Quoting
 By. William Long, Date: 2026-05-12

Arrived at customer location and located truck, removed the floor and lower part of the dash and adjusted the parking brake handle and tested with no issues and put back together.
 By. William Long, Date: 2026-06-16

Work Order
 340120869

Date Completed
 2026-06-16

Work Order Type
 Service

Person
 William Long

Reference
 TQ391783

Equipment
 S/N: 10222914
 Make: CROWN
 Model: C51000-50
 Meter: 3408.2
 Unit No.: 10222914 / Internal No.: 10222914

Parts

Date	Person	Part	Description	Location	Quantity
------	--------	------	-------------	----------	----------

Travel & Labor

Date	Person	Type	Quantity
2026-06-16	William Long	LABOR	1.00
2026-05-12	William Long	LABOR	1.50
		TOTAL LABOR	2.50
		TOTAL TRAVEL	0.00

Signed By: William Long

Cancellation of Service: In the event that the customer cancels any repair work or denies any repairs that were quoted, the unit shall be reassembled to a condition reasonably similar as when first inspected unless customer waives reassembly or the reassembled unit would be unsafe. Customer will be responsible for charges incurred during teardown, the cost of parts and labor to replace items destroyed in teardown and the cost to reassemble.

Limited Warranty: All materials, parts and equipment are warranted by the manufacturer or suppliers written warranty only. All labor performed by the above named company is warranted for a period of 90 Days unless otherwise noted in writing. the above named company makes no other warranty, express or implied and its agents or technicians are not authorized to make any such warranties on behalf of the above named company. Terms: NET 30 Days



1500 Jimmy Deloach Pkwy, Suite 100
Pooler, GA 31415
912-447-9500
liftpower.com

Customer

SHIP8 INC
311 INTERNATIONAL TRADE PKWY
Savannah, GA 31407
510-490-9788
PO Number: 26060655

Work Order
340120869

Work Order Type
Service

Reference
TQ391783

Equipment

S/N: 10222914
Make: CROWN
Model: C51000-50
Meter: 3408.2
Unit No.: 10222914 / Internal No.: 10222914

Date Completed
2026-06-16

Person
William Long

William Long

Re: Completed: You're copied on "06092026-SD2- 934007584-LiftPower"

From Patrick Andreshack <patrick.andreshack@ship8.com>

Date Wed 6/17/2026 10:23 AM

To Christine Jenkins <christine.jenkins@ship8.com>; Angele White <Angele.White@ship8.com>; James Burford <james.burford@ship8.com>

completed



SHIP8INC.

Patrick Andreshak
Maintenance Manager
550 Northport Parkway
Port Wentworth, GA 31407

C:912.414.6118

From: Christine Jenkins <christine.jenkins@ship8.com>

Sent: Wednesday, June 17, 2026 9:46 AM

To: Angele White <Angele.White@ship8.com>; James Burford <james.burford@ship8.com>

Cc: Patrick Andreshack <patrick.andreshack@ship8.com>

Subject: Re: Completed: You're copied on "06092026-SD2- 934007584-LiftPower"

Team

Has PO 26060655 been completed?



SHIP8INC.

Christine Jenkins
Purchasing Coordinator
550 Northport Parkway



Industrial Trucks - Material Handling Equipment
 6801 Suemac Place
 Jacksonville, FL 32254
 (904) 783-0250 | Fax (904) 781-1451

Inv # 340120869
 Reference # 934007584
 Inv Date 6/16/2026
 Terms - Net 30
 Writer: TQ391783

Road Service Invoice

Salesman: House CSSR

BILL	SHIP
TO: 7253	TO: 7255
SHIP8 INC	SHIP8 INC
45875 NORTHPORT LOOP EAST	SD3
Fremont, CA 94538	311 INTERNATIONAL TRADE PKWY
510-490-9788	Savannah, GA 31407
	510-490-9788

PO #	Ship Via	FOB	Make	Model	Serial #	Unit #	Meter
26060655			CROWN	C51000-50	10222914	10222914	3408.2

Inspect & quote. DO NOT COMPLETE ANY REPAIRS WITHOUT QUOTING FIRST. Parking brake needs adjustments, difficulty in moving. Brakes making a squeezing noise when driving fwd. PM Follow Up Jimmie Al.

This time has been added to quote 934007584

WORK PERFORMED: Inspected the truck and found that the service brake handle was adjusted up to much causing it to bind, need to adjust brake handle so it pulls back with ease and releases the same. Quoting William Long (2026-05-12)

Arrived at customer location and located truck, removed the floor and lower part of the dash and adjusted the parking brake handle and tested with no issues and put back together. William Long (2026-06-16)

Part #	Whse	Description	Bin	Extended
		Labor		404.25

Need to place a service call?

Please visit our website www.liftpower.com, click on service request, fill out the form and click submit. The next available service technician will be dispatched to you.

Invoices sent to collections will be subject to additional costs associated with collection of a debt over and above the original debt amount.

Sub Total	\$404.25
Tax	\$0.00
Total	\$404.25