





KOHL'S INSPECTION FORM



KEY / CODE

- 1. DENTED
- 2. SCRATCHED
- 3. TORN
- 4. HOLE
- 5. BROKEN
- 6. MISSING
- 7. BENT
- 8. CRACKED
- 9. FLAT TIRE
- 10. BALD TIRE
- 11. LEAKING AIR
- 12. LICENSE PLATE MISSING
- 13. TAGS EXPIRED
- 14. DOT INSPECTION TAG
- 15. MUD FLAPS
- 16. OTHER

PLEASE ADVISE DISPATCH/SAFETY IF MAJOR DAMAGE IS NOTED ON ANY TRAILER

DRIVER NAME: Cosmo Victor

DRIVERS SIGNATURE: _____

DATE: 10/9/19 TIME OUT: _____ TIME IN: 15:54

COMPANY NAME: Prestige

CONTAINER NUMBER: UESB4713239

SEAL NUMBER: 41100558

DESTINATION: Gre

KEY CODE#



EMPTY



LOADED



COMMENTS:

BACK OF TRAILER

FRONT OF TRAILER

JARD SIGNATURE:

[Handwritten signature]

PRINT NAME:

James Juan

GBINQ06R
KIMARA

GILBERT COMPANIES
Kohls Container Number Inquiry

10/10/19
14:29:49

Type option, press Enter.

1=Receipt 2=Manifest

UESU4773239

<u>Container#</u>	<u>Consignee</u>	<u>Receipt#</u>	<u>Manf#</u>	<u>Pcs</u>	<u>Wght</u>	<u>Adv</u>	<u>Chrg</u>
UESU4773239	KIL890	8604832	208518	601	6010		.00
UESU4773239	KIL890	8604850	208518	7	70		.00
UESU4773239	KMO840	8604826	515633	350	3500		.00
UESU4773239	KMO840	8604844	0	5	50		.00
UESU4773239	KNY865	8604829	208505	613	6130		.00
UESU4773239	KNY865	8604847	208505	13	130		.00
UESU4773239	KCA885	8604831	520745	210	2100		.00
UESU4773239	KCA885	8604849	0	5	50		.00
UESU4773239	KOH810	8604823	208502	1	10		.00
UESU4773239	KOH810	8604824	208502	666	6660		.00
UESU4773239	KOH810	8604842	208502	17	170		.00
UESU4773239	KCA855	8604827	514741	268	2680		.00
UESU4773239	KCA855	8604845	0	5	50		.00

More...

F3=Exit F5=Refresh

GBINQ06R
KIMARA

GILBERT COMPANIES
Kohls Container Number Inquiry

10/10/19
14:29:49

Type option, press Enter.
1=Receipt 2=Manifest

UESU4773239

<u>Container#</u>	<u>Consignee</u>	<u>Receipt#</u>	<u>Manf#</u>	<u>Pcs</u>	<u>Wght</u>	<u>Adv</u>	<u>Chrg</u>
UESU4773239	KVA830	8604825	208514	531	5310		.00
UESU4773239	KVA830	8604843	208514	9	90		.00
UESU4773239	KTU860	8604828	524547	209	2090		.00
UESU4773239	KTU860	8604846	0	4	40		.00
UESU4773239	KGA875	8604830	0	386	3860		.00
UESU4773239	KGA875	8604848	0	8	80		.00

Bottom

F3=Exit F5=Refresh

10/10/19
12:07:32

GILBERT COMPANIES
Create Deconsol Bills by Container

KIMARA
KH026R

Container#: UESU4773239
Howland Hook PU .: N

Total Cartons:3908

Type option, press Enter.
4=Remove

<u>PO#</u>	<u>Quantity</u>
- 12417926	1
- 12417933	3907

F05=Refresh F10=Create F12=Previous

Bottom

K865



RECEIPT NUMBER	RECEIVING DATE
4133652	10/11/19

RECEIVED FOR THE ACCOUNT OF
ADHLS DC 865 3440 STATE RDUT

MURTSBORO, NY 12790

SHIPPER
LI & FUNG (TRADING) LIMIKEASBEY, NJ 08832

The Gilbert Company

1000 RIVERSIDE DRIVE • KEASBEY, NJ 08832 • (732) 709-5330 • FAX (732) 709-5501

TERMS AND CONDITIONS. It is understood that this consolidator shall not be liable for more than the limits of it's liability for loss, fixed at and limited to \$1.00 per each garment up to a maximum aggregate of \$25.00 per shipment unless a greater value is declared at the time of shipment and charges paid for such greater value at the rate of 30 cents per \$100.00 of declared value or fraction thereof.

CARRIER	PPD/COL	ADVANCED CHARGES	PRO NUMBER	PICK-UP NUMBER
GILBERT EAST	C	.00	417920	

DRIVER NUMBER	B L #	B L DATE	BATCH NO.
KIMARA	UESU4773239	10/11/19	10/11/19

QTY EXPECTED	TYPE FRT.	WGT.	DESCRIPTION
5/ 5	C	1	FREE ASTRAY

DEPT#:
PO# 12417920 PO# PO#

****PO NOT FOUND ****

01 SHORT	02 OVER
03 IMPORT	04 RECOUPED U
05 WET CARTON	06 DAMAGE/CRU
07 PILFERAGE	08 R/SHPRS TA

ALL SHIPMENTS RECEIVED SUBJECT TO INSPECTION AT FINAL DESTINATION.
CONSOLIDATOR NOT LIABLE FOR CONCEALED DAMAGES OR SHORTAGES.

QTY RECEIVED	CHECKER ID	QTY LOADED	LOADER ID	LOAD SEQUENCE
5	80			

COMMENTS:

RECEIPT NO.

DRIVER SIGNATURE 4133652
GEC AUTHORIZED SIGNATURE