


PO 104959
Interior Visions Inc.
Olliix Order #20758091

Received on 11/29/2023

Inspected on 11/30/2023

Item #II95C-0149, Misty Sunset Canvas
Received with 3 areas of concealed damage.
WILL KEEP AS IS WITH A FAIR DISCOUNT

1. Canvas is very loose
Due to weight
On carton during shipping



2. Cracked Stretcher
Bar on frame



3. Stretcher Bar on
Frame broken loose
at one end